



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22000550/Tqf3e2	
			Date: 12/04/2022	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBE 7691J	Veh. Inspected	SKG 3527K
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000165MFCV	Excess (\$)	0.00
	Assign From	AINI BINTE	Assign Date	14/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ C 200	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	WDD2040412A319757	Colour	BLACK
	Odometer	134183 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	235/35 R19	ROTALLA	6 mm
	L/H Front Tyre	235/35 R19	ROTALLA	6 mm
	R/H Rear Tyre	235/35 R19	ROTALLA	6 mm
	L/H Rear Tyre	235/35 R19	ROTALLA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	13/01/2022	Inspection Date	17/01/2022
	Survey held at	Blk 8 Kaki Bukit Ave 4 #05-23 Premier @ Kaki Bukit		
	Repairer	XIN YUN AUTO PTE LTD		
<b>5a. Remarks</b>				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	