

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000552/BVF3N2**Date:** 23/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN00122132101

Claimant Vehicle No : SKN1301X **Insured Vehicle No :** GBL600G

Date of Loss: 13/01/2022 Nature of Claim: TP Claim No: SNM22D200366/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKN1301X**

Make & Model: AUDI A4, 1.8 TFSI MU (A) Engine No: CJE070014

Reg. Date: 15/05/2014 (Man. Year: 2013) Chassis No: WAUZZZ8K4EA071627

Colour: Red Odometer: 105242 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35ZR19 Rear Tyre Size: 245/35ZR19

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,784.50	6,758.67	21,025.83	75.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,140.00	1,960.00	3,180.00	61.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,924.50	8,718.67	24,205.83	73.52
Approved Total (Overridden) (S\$)		6,950.00		
(S\$)	32,924.50	6,950.00	25,974.50	78.89
+ GST 7.00/7.00% (S\$)	2,304.72	486.50	1,818.22	78.89
Nett Amount (S\$)	35,229.22	7,436.50	27,792.72	78.89

INSPECTION

Date of Assignment: 07/02/2022

Date Inspected: 21/01/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Feb 2022)
Parts: 143	AUDI A4 1.8 TFSI MU (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKN1301X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Damaged	2,246.00 FL	*- FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	112.00 FL	*- FL
3	1		*RH HEADLAMP ASSY	Not Damaged	3,273.00 FL	*- FL
4	1		*RH FRONT FENDER	Not Damaged	767.00 FL	*- FL
5	1		*RH FRONT FENDER SPLASH SHIELD	Not Damaged	241.00 FL	*- FL
6	1		*RH FRONT LOWER ARM	Not Damaged	378.00 FL	*- FL
7	1		*RH FRONT KNUCKLE ARM	Not Damaged	638.00 FL	*- FL
8	1		*RH FRONT SHOCK ABSORBER	Not Damaged	266.00 FL	*- FL
9	1		*RH FRONT WHEEL BEARING	Not Damaged	379.00 FL	*- FL
10	1		*RH SIDE MIRROR ASSY	Not Damaged	897.00 FL	*- FL
11	1		*RH SIDE MIRROR COVER	Not Damaged	292.00 FL	*- FL
12	1		*RH SIDE MIRROR SIGNAL LAMP	Not Damaged	89.00 FL	*- FL
13	1		*RH FRONT DOOR	Repair	2,198.00 FL	*- FL
14	1		*RH FRONT DOOR WEATHERSTRIP	Not Damaged	185.00 FL	*- FL
15	1		*RH REAR DOOR	Dented	2,063.00 FL	*2,063.00 FL
16	1		*RH REAR DOOR WEATHERSTRIP	Necessary	185.00 FL	*185.00 FL
17	1		*REAR WINDSCREEN GLASS WITH RUBBER SEAL	Not Damaged	1,672.00 FL	*- FL
18	1		*RH REAR FENDER	Dented	1,973.00 FL	*1,820.00 FL
19	1		*RH REAR LOWER ARM	Not Damaged	853.00 FL	*- FL
20	1		*RH REAR KNUCKLE ARM	Not Damaged	993.00 FL	*- FL
21	1		*RH REAR SHOCK ABSORBER	Not Damaged	433.00 FL	*- FL
22	1		*RH REAR WHEEL BEARING	Not Damaged	443.00 FL	*- FL
23	1		*RH REAR UPPER ARM	Not Damaged	448.00 FL	*- FL
24	1		*RH REAR LATERAL ARM	Not Damaged	505.00 FL	*- FL
25	1		*RH REAR TRACK ROD	Not Damaged	223.00 FL	*- FL
26	1		*RH TAILLAMP ASSY	Not Damaged	1,019.00 FL	*- FL
27	1		*REAR BUMPER	Broken	2,015.00 FL	*1,778.75 FL
28	4		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	12.00 FL	*12.00 FL
29	1		*REAR BUMPER RH SIDE RETAINER	Necessary	112.00 FL	*80.90 FL
30	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
31	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS
32	1		*RH FRONT SPORT RIM	Not Necessary	1,450.00 FS	*- FS
33	1		*RH FRONT TYRE	Not Damaged	450.00 FS	*- FS
34	1		*RH REAR SPORT RIM	Cut	1,450.00 FS	*746.00 FS
35	1		*RH REAR TYRE	Cut	450.00 FS	*250.00 FS
36	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
37	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
38	1		*REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	29,030.00	7,055.65
- List Item Discount on L Items 5.00/5.00% (S\$)	1,245.50	296.98
Total Parts (S\$)	27,784.50	6,758.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,800.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	20.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	20.00
5	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	60.00
6	REMOVE AND REINSTALL ROOF LINING,SEATS,GARNISH,BOARDS AND CARPET TO ASSIST REPAIR	New	550.00	0.00
7	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	300.00	0.00
8	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	60.00
9	REMOVE AND REINSTALL RH REAR DOOR INNER MECHANISM TO ASSIST REPAIR	New	180.00	80.00
10	REMOVE AND REINSTALL RH FRONT DOOR INNER MECHANISM TO ASSIST REPAIR	New	180.00	0.00
11	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	300.00	0.00
12	RESET AND DIAGNOSE CONTROL UNIT AND FAULT CODE	New	250.00	120.00
Gross Labour Cost (\$\$)			5,140.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >