

ASS. REC. BY:

REF:

TY / 220005531K

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHF 7417 Yr Regn: 06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude c.c. 1995Colour M. White / Red A/C: Insured / Std / NI / NASp. Reading 471425 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABL15AUC 282727Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: M11 / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Skilun

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 13/1/22 D.O.I. 17/1/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/1/22 11:30 83900L Cur

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF741T**AAD2201-***Not Notified*
11 Pmp @ 3900/h

Vehicle No.:

Chassis No.:

17 JAN 2022

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF741T

VF1ABL15AUC282727

RENAULT

LATITUDE

13/01/2022

III

30/06/2016

PART**LIST**

1 BUMPER COVER REAR	\$	<i>R</i>	561.70	✓
1 BUMPER LOWER REAR	\$	<i>R</i>	411.90	X
1 BUMPER BRACKET CTR REAR	\$	<i>R</i>	98.10	X
1 BUMPER BRACKET SIDE RH REAR	\$	<i>R</i>	82.10	X
1 BUMPER REFLECTOR RH	\$	<i>CM</i>	16.60	✓
1 BUMPER RETAINER RH REAR	\$	<i>R</i>	59.80	X
1 BUMPER BRACKET SIDE LH REAR	\$	<i>R</i>	80.80	X
1 BUMPER RETAINER LH REAR	\$	<i>R</i>	54.20	X
1 BUMPER BEAM REAR	\$	<i>R</i>	547.80	✓
1 OUTER PANEL REAR (End Panel)	\$	<i>R</i>	745.80	X
1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>R</i>	404.56	X
1 TAILLAMP LH	\$	<i>R</i>	401.40	X
1 TAILLAMP RH	\$	<i>CM</i>	401.40	✓
1 BOOT REAR	\$	<i>R</i>	1,677.20	✓
1 BOOT BADGE 'RENAULT'	\$	<i>R</i>	82.40	✓
1 BOOT BADGE	\$	<i>R</i>	95.80	✓
1 BOOT HINGE LH	\$	<i>R</i>	254.20	X
1 BOOT HINGE RH	\$	<i>R</i>	254.20	X
1 BOOT STRUT LH	\$	<i>R</i>	145.10	X
1 BOOT STRUT RH	\$	<i>R</i>	145.10	X
1 BOOT LOCK	\$	<i>R</i>	246.60	X
1 BOOT LOCK CATCH	\$	<i>R</i>	41.70	X
1 BOOT FINISHER	\$	<i>R</i>	344.70	X
	\$		7,153.16	
	10% \$		715.32	
	\$		6,437.84	

Special Nett

Trans-cab Auto Services Pte Ltd**AAD2201-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF741T

1SET PARKING AID	\$	shan 700.00	400.00
1SET REAR BUMPER CLIP	\$	nn 66.00	—
1 FENDER CLIP	\$	nn 60.00	X
1SET BUMPER BRACKET CTR CLIP	\$	nn 33.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	nn 20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn 10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	nn 20.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn 66.00	X
1 REAR BOOT STICKER 'Trans-cab'	\$	nn 80.00	30.00
1 REAR BOOT STICKER '6555-3333'	\$	nn 80.00	30.00
2 WINDSCREEN SEALANT	\$	nn 150.00	X
1 WINDSCREEN MOULDING	\$	nn 200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	nn 130.00	X
TOTAL	\$	1,625.00	
TOTAL PARTS	\$	8,062.84	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	500
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	660
To Rust-Proofing Of The Affected Areas.	\$	170.00	30
To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD2201-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF741T

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>

TOTAL \$ 7,580.00**Over All Total \$ 22,080.69****(LUMP SUM)****Repair Days***20 DAYS**3 days***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: