

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000554/UVF3N2**Date:** 30/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00149832101

**Claimant Vehicle
No :** FBL4911H**Insured Vehicle
No :** SFV19K

Date of Loss: 12/01/2022

Nature of Claim: TP

Claim
No: SNM22D200302/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **FBL4911H**

Make & Model: SUZUKI BURGMAN, 400cc ABS

Engine No: K432182871

Reg. Date: 15/11/2016 (Man. Year: 2016)

Chassis No: JS1CG1131G0101697

Colour: Grey

Odometer: 61962 km

Engine Capacity: 400 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60-14

Rear Tyre Size: 150/70-13

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,271.10	5,125.00	14,146.10	73.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	810.00	830.00	50.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,911.10	5,935.00	14,976.10	71.62
Approved Total (Overridden) (\$\$)		4,700.00		
Nett Amount (\$\$)	20,911.10	4,700.00	16,211.10	77.52

INSPECTION

Date of Assignment: 14/01/2022

Date Inspected: 17/01/2022 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 May 2022)	
Parts:	N/A	SUZUKI BURGMAN 400cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL4911H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	438.00 FL	*235.00 FL
2	1		*FRONT FAIRING	Repair	850.00 FL	*- FL
3	1		*LOWER BELLY PANEL	Cut	425.00 FL	*425.00 FL
4	1		*HEADLAMP ASSY	Cut	1,480.00 FL	*1,100.00 FL
5	1		*HEADLAMP COVER	Repair	425.00 FL	*- FL
6	1		*FRONT FORK ASSY	Serviceable	2,200.00 FL	*- FL
7	1		*FORK UNDER BRACKET	Not Necessary	480.00 FL	*- FL
8	1		*FRONT RIM	Not Necessary	1,200.00 FL	*- FL
9	2		*FRONT BRAKE DISC	Not Necessary	960.00 FL	*- FL
10	1		*FRONT RIM SHAFT	Not Necessary	180.00 FL	*- FL
11	1		*FRONT RIM BEARING	Not Necessary	85.00 FL	*- FL
12	1		*WINDSHIELD	Not Necessary	1,100.00 FL	*- FL
13	1		*SIDE MIRRORS	O/s Cut/N/s Not Necessary	286.00 FL	*125.00 FL
14	1		*HANDLE BAR	Bent	380.00 FL	*290.00 FL
15	1		*HANDLE BAR ENDS	O/s Cut/N/s Not Necessary	120.00 FL	*45.00 FL
16	2		*HAND GRIPS	Not Necessary	80.00 FL	*- FL
17	1		*BRAKE LEVERS	O/s Cut	320.00 FL	*110.00 FL
18	1		*FOOTSTEP PANEL	O/s Cut	580.00 FL	*250.00 FL
19	1		*FOOTSTEP LOWER PANEL	O/s Cut	480.00 FL	*200.00 FL
20	1		*EXHAUST ASSY	Dented/Bent	2,100.00 FL	*1,600.00 FL
21	1		*EXHAUST PROTECTOR	Cut	180.00 FL	*125.00 FL
22	1		*EXHAUST END CAP	Cut	140.00 FL	*60.00 FL
23	1		*REAR LAMP ASSY	Cracked	685.00 FL	*580.00 FL
24	1		*REAR LAMP LOWER COVER	Cracked	280.00 FL	*145.00 FL
25	1		*REAR ABSORBER	Not Necessary	2,585.00 FL	*- FL
26	1		*ENGINE MOUNTING	Not Necessary	2,000.00 FL	*- FL
27	1		*REAR MUDGUARD	Deformed	380.00 FL	*300.00 FL
28	1		*SET NUMBER PLATE	Rear Bent	38.00 FS	*14.00 FS
29	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
30	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
31	1		*SET STEERING CONE	Not Necessary	90.00 FS	*- FS
32	1		*REAR BOX	Serviceable	380.00 FS	*- FS
33	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
34	1		*STICKER	Necessary	120.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,313.00	5,684.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,041.90	559.00
Total Parts (\$\$)	19,271.10	5,125.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD)	New	60.00	60.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	420.00	350.00
4	TO REPAIR BODY FRAME	New	480.00	0.00
5	TO RESPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (\$)			1,640.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >