



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 9585L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER LH (CONSISTENT)	DENTED	560.20	560.20
1	FRONT DOOR LH (CONSISTENT)	DENTED	1,355.20	1,125.00
1	FRONT DOOR HINGE (UPPER) LH (CONSISTENT)	NOT NECESSARY	63.00	-
1	FRONT DOOR HINGE (LOWER) LH (CONSISTENT)	NOT NECESSARY	63.00	-
1	FRONT DOOR INNER LOCK LH (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT DOOR INNER TRIM BOARD LH (CONSISTENT)	NOT NECESSARY	530.00	-
1	FRONT DOOR REGULATOR LH (CONSISTENT)	DAMAGED	230.00	230.00
1	FRONT DOOR POWER WINDOW MOTOR LH (CONSISTENT)	DAMAGED	210.00	210.00
1	REAR DOOR LH (CONSISTENT)	DENTED	1,355.20	1,049.00
1	ROCKER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	860.20	-
	LESS 20% DISCOUNT		-1,101.36	-634.84
			4,405.44	2,539.36
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT DOOR TRIM BOARD CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
			20.00	20.00
<u>LABOUR</u>				
	PANEL BEATING ,REMOVAL AND REPLACING PARTS .INCLUSIVE OF THE REPAIR OF ROCKER PANEL .		1,200.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	800.00
	TUFF COAT.		250.00	60.00
	WIRING CHECK .		180.00	30.00
	TO TRANSFER FRONT DOOR MECHANISM .		180.00	80.00
	TO TRANSFER REAR DOOR MECHANISM .		180.00	80.00
			3,190.00	1,850.00
GRAND TOTAL			7,615.44	4,409.36



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00
---	--	--	-----------------

Report Ref No. CC4/ASM22000561/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.