



			<b>Total</b>	<b>\$ 15,191.10</b>
--	--	--	--------------	---------------------

No.	Special Nett Items		Amount
1	RH rear sport rim		
2	RH rear tyre	1	\$ 980.00
3	Brake fluid	1	\$ 420.00
4	RH rear fender joint sealant	1	\$ 50.00
5	RH rear fender inner trim board clips	1set	\$ 70.00
6	RH rear door inner trim board clips	1set	\$ 50.00
7	RH front door inner trim board clips	1set	\$ 60.00
8	RH side door centre pillar joint sealant	1set	\$ 60.00
		1	\$ 70.00

Scr PTC 650  
 X SVC  
 X NN  
 40 nec  
 40 25 nec  
 30 MC  
 30 MC  
 X NN

	Labour and painting		Amount
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas		\$ 1,600.00
2	Spray painting on affected areas and panels		\$ 1,400.00
3	Check wiring and lighting system		\$ 80.00
4	Apply rust coating chemical on affected areas and panels		\$ 120.00
5	Remove and replace RH front door inner mechansim to new door		\$ 150.00
6	Remove and replace RH rear door inner mechansim to new door		\$ 150.00
6	Remove and reinstall RH side door centre pillar inner garnish to assist repair		\$ 250.00
7	Test drive and adjust wheel alignment system		\$ 100.00
8	Remove and replace rear undercarriage parts to assist repair		\$ 400.00
9	Remove and reinstall roof lining, seats, seat belts, carpet and boards to assist repair		\$ 480.00
10	Remove and reinstall rear bumper reverse sensors to assist repair		\$ 100.00

1000  
 1200  
 30  
 40  
 50  
 50  
 X NN  
 60  
 ? X NN  
 120  
 30

thuvan@khaato.com

**Total Amount:**

**\$ 21,781.10**

82235769

19/11/22 1130

LIS wp 7 days

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

**Supplementary estimate**

Vehicle number: SKT8447G

Make & Model: Mercedes Benz A180

No.	Description of spare parts	Qty	List price	Amount
1	Front bumper	1		\$ 1,168.00
2	Front bumper lip	1		\$ 245.00
3	Front bumper RH side retainer	1		\$ 32.00
4	Front bumper LH side retainer	1		\$ 32.00
5	Front bumper RH distance sensor	1		\$ 189.00
6	Front bumper distance sensor rubber seal	4		\$ 24.00
7	RH headlamp assy	1	is42	\$ 2,405.00
8	RH side mirror assy	1		\$ 894.00
9	RH side mirror cover	1	203	\$ 310.00
10	RH front fender	1		\$ 672.00
11	RH front fender shield splash	1		\$ 178.00
12	RH front lower arm	1		\$ 583.00
13	RH front knuckle arm	1		\$ 988.00
14	RH front wheel bearing	1		\$ 452.00
15	RH front shock absorber	1		\$ 742.00
16	RH front control arm	1		\$ 382.00
17	RH front tie rod end	1		\$ 118.00
			Total	\$ 9,414.00
			Less 10%	\$ 1,882.80
			<b>Total</b>	<b>\$ 7,531.20</b>

/ cut  
 / CRG  
 / nec  
 / Src  
 / cut  
 / nec  
 / cut  
 / jam  
 / scr  
 / cut  
 / src  
 / src  
 / h  
 / htu

Special Nett.			
1	Front bumper clips	1set	\$ 70.00
2	Front bumper lower RH diffuser	1	\$ 70.00
3	RH front fender shield splash clips	1set	\$ 70.00
4	RH front wheel	1	\$ 980.00
5	RH front tyre	1	\$ 420.00

30 nec  
 / XNW  
 / 30 nec  
 / scr 650  
 / scr

Labour			
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas (front portion)		\$ 1,000.00
2	Spray painting on affected areas and panels		\$ 800.00
3	Check wiring and lighting system		\$ 80.00
4	Remove and replace front undercarriage parts to assist repair		\$ 550.00

200

XNN

~~XNN~~ XNN

KIU XNN

**Total Amount**

**\$11,571.20**

F: 14750

RP: 8.