



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22000562/Vqf3e2 Date: 19/08/2022 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SHD 6339T	<b>Veh. Inspected</b>	SKT 8447G
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	TAX/01/22/2021	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HUA YEN	<b>Assign Date</b>	15/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	MERCEDES BENZ A180	<b>c.c</b>	1595
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	WDD1760422J376955	<b>Colour</b>	BROWN
<b>Odometer</b>	110860 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/40Z R18	DUNLOP	6 mm
<b>L/H Front Tyre</b>	225/40Z R18	DUNLOP	6 mm
<b>R/H Rear Tyre</b>	225/40Z R18	DUNLOP	6 mm
<b>L/H Rear Tyre</b>	225/40Z R18	DUNLOP	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	13/01/2022	<b>Inspection Date</b>	19/01/2022
<b>Survey held at</b>	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>	