

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

**Supplementary estimate**

Vehicle number: SKT8447G

Make & Model: Mercedes Benz A180

No.	Description of spare parts	Qty	List price	Amount
1	Front bumper	1		\$ 1,168.00
2	Front bumper lip	1		\$ 245.00
3	Front bumper RH side retainer	1		\$ 32.00
4	Front bumper LH side retainer	1		\$ 32.00
5	Front bumper RH distance sensor	1		\$ 189.00
6	Front bumper distance sensor rubber seal	4		\$ 24.00
7	RH headlamp assy	1	is42	\$ 2,405.00
8	RH side mirror assy	1		\$ 894.00
9	RH side mirror cover	1	203	\$ 310.00
10	RH front fender	1		\$ 672.00
11	RH front fender shield splash	1		\$ 178.00
12	RH front lower arm	1		\$ 583.00
13	RH front knuckle arm	1		\$ 988.00
14	RH front wheel bearing	1		\$ 452.00
15	RH front shock absorber	1		\$ 742.00
16	RH front control arm	1		\$ 382.00
17	RH front tie rod end	1		\$ 118.00
			Total	\$ 9,414.00
			Less 10%	\$ 1,882.80
			<b>Total</b>	<b>\$ 7,531.20</b>

/ cut  
 / CRG  
 / nec  
 / Src  
 / cut  
 / nec  
 / cut  
 / jam  
 / scr  
 / cut  
 / src  
 / src  
 / h  
 / htu

Special Nett.				
1	Front bumper clips	1set		\$ 70.00
2	Front bumper lower RH diffuser	1		\$ 70.00
3	RH front fender shield splash clips	1set		\$ 70.00
4	RH front wheel	1		\$ 980.00
5	RH front tyre	1		\$ 420.00

30 nec  
 / XNW  
 / 30 nec  
 / scr 650  
 / scr

Labour			
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas (front portion)		\$ 1,000.00
2	Spray painting on affected areas and panels		\$ 800.00
3	Check wiring and lighting system		\$ 80.00
4	Remove and replace front undercarriage parts to assist repair		\$ 550.00

200

XNN

~~XNN~~ XNN

XIV XNN

Total Amount

\$11,571.20

F: 14750

RP: 8