

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 18 Jan 2022

Preliminary Advice

Vehicle No	: SFR8000G	Accident Date	: 12/01/2022
Make	: TOYOTA HARRIER 2.0	Policy No.	: MPC21A00043604
Assignment Date	: 14/01/2022	Excess	: S\$0.00
Date of Inspection	: 17/1/2022	Est. Duration of Repair	: 6
Inspection At	: RICARDO AUTO CENTRE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,558.90
Revised Amount	:S\$	7,871.40
Check Items (Estimated)	:S\$	1,475.50
Total	:S\$	9,346.90
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	60,878.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,122.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on part by part

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .