

(SUPPLEMENTARY)

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC21A00043604	Date of Loss:	12/01/2022
Vehicle Reg. No.:	SFR8000G	Driveable?	YES
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	DU NINI	Contact No:	+6593824932
Make/Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Vehicle Reg. Date:	12/05/2017
Vehicle Colour:	Maroon	Chassis No:	ZSU600106307
Engine No:	3ZRC004933		
Odometer:	28464 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	9		

Description of Accident/Loss REFER TO GIA REPORT

Present Location: RICARDO AUTO CENTRE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	553.30
Miscellaneous Items	40.00
Labour	120.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	713.30
+ GST 7.00% (S\$)	49.93
Nett Amount (S\$)	763.23
+ Previous Estimates (S\$)	11,565.52
Claim Total (S\$)	12,328.75

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 28 Jan 2022)
Parts:	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Ricardo Auto Centre Pte Ltd/SFR8000G/28/01/2022 12:47	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Radiator support garnish RH (big) ✓ De	0.00	0.00	*35.00 F
2	1		*Radiator support garnish LH (small) ✓ De	0.00	0.00	*25.00 F
3	1		*Radiator support garnish LH (big) ✓ De	0.00	0.00	*45.00 F
4	1		*Fog lamp cover LH ✓ Cut	0.00	0.00	*48.00 F
5	1		*Rear windscreen glass moulding lower ✓ NEC	0.00	0.00	*40.00 F
6	1		*Rear windscreen glass moulding side LH ✓ NEC	0.00	0.00	*25.00 F
7	1		*Rear windscreen glass moulding side RH ✓ NEC	0.00	0.00	*25.00 F
8	1		*Front support panel - center ✓ BT	0.00	0.00	*150.00 F
9	1		*Bonnet moulding ✓ Mis	0.00	0.00	*110.00 F

F=Franchise part.

Sub Total (\$)	503.00
+ Margin on L,N Items 10.00% (\$)	50.30
Total Parts (\$)	553.30

Ricardo Auto Centre Pte Ltd/SFR8000G/28/01/2022 12:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	To supply windscreen sealant ✓ NEC	40.00
Sub Total (\$\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove back windscreen glass enable to replace new tailgate and fix same.	New	120.00 ✓
Gross Labour Cost (\$\$)			120.00

Ricardo Auto Centre Pte Ltd/SFR8000G/28/01/2022 12:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >