

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GBB2096B

Model: TOYOTA HIACE

Accident Date : 15/1/2022

26/9/2008

Location : MANDAI ROAD TOWARDS BKE EXIT

3P: GBE3594H(AIG)

Acknowledged by Repairer

Signature: [Signature]

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper	656.20		
2	1 pc	Rear bumper o/s & n/s retainer	182.70		
3	10 pcs	Rear bumper clips		30.00	70
4	4 pcs	Rear centre bracket	80.00		
5	1 pc	Rear tail-gate	1,925.90		
6	1 pc	Rear tail-gate weatherstrip	320.00		
7	1 pc	Rear tail-gate inner trim	210.00		
8	6 pcs	Rear tail-gate inner trim clips		24.00	12
9	1 pc	Rear tail-gate 'TOYOTA' emblem	82.00		
10	1 pc	Rear tail-gate '70 KMPH' emblem		15.00	10
11	1 pc	Rear tail-gate moulding Garnish	310.40		
12	6 pcs	Rear tail-gate moulding clips		24.00	12
13	1 pc	Rear tail-gate lock (upper)	172.00		
14	1 pc	Rear tail-gate lock (lower)	81.5		
15	1 pc	Rear tail-gate lock actuator	365.60		
16	1 pc	Rear o/s & n/s tail lamp	891.20		
17	1 pc	Rear end panel (outer)	596.00		
18	1 pc	Rear end panel garnish chrome	210.50		
19	1 pc	Rear windscreen solar film		150.00	
20	1 pc	Rear windscreen moulding		120.00	60
21	1 pc	Rear windscreen sealant		80.00	40
22	1 pc	Rear windscreen	1,556.80		
23	1 pc	Rear reg. no. plate		35.00	
24	2 pcs	Rear reg. no. plate lamp XI	185.40		
25	1 set	Rear reverse sensor		280.00	200
26	1 pc	Rear reverse camera		300.00	
		Rear spare wheel tyre bracket \$210.5	7,744.70	1058.00	0.00
		Rear carpet \$295.2	25%	0%	10%
		After Less %:	5,808.53	1058.00	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		800.00	
2		To spray painting.		600.00	
3		To remove & replace rear windscreen		140.00	
4		To remove and replace rear reverse camera		100.00	
5		To remove and refit rear tail gate		80.00	
6		To remove and replace rear tail gate aluminium		80.00	
7		To remove and refit rear upholstery to facilitate repair		80.00	
8		To check wiring.		80.00	
9		To re-seal anti-rust.		50.00	
		Sub-Total:		2,010.00	
		Total:		8,876.53	
		After less 20%:		7,101.22	

BT
nec
nec
XR
BT
Cut
XSVC
nec
nec 60
nec
Cut 289
nec
jam
XSVC
jam
Cra 791.6
BT
XR
XNN
nec
40
nec
Cra 1115.2
IST
Cra 58
Cut
XNN
BT 172.1
XSVC
Vans
2000
170
XNN
40
40
30
20
20
5500

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Thevan@lkhauto.com
82235769 1/5 wp 5 days
17/1/22 1600



AL 8778 1999
24 hr accident call

