

LKK Auto Consultants hence notify the Repairer of the following: to resurvey before/after spray painting. To disassemble parts during resurvey. Parts prices are subject to confirmation. Third party survey is on a "Without Prejudice" basis. No illegal modification(s) is allowed.

**ESTIMATE OF REPAIR** to be resurveyed and is subject to final approval from Insurance Company.

Signature: [Signature] Model: TOYOTA NOAH HYBRID

2 Kaki Bukit Ave 2, #02-1922, Singapore 417921  
 Email: ryderautoworkshop@gmail.com  
 Tel: 67448277 Fax: 67468277

Thuan@Lhhauto.com  
 82235769  
 17/1/22 1530  
 5 days w/p

Veh# : SMQ2070R  
 Accident Date : 14/1/2021  
 Location : CTE TOWARDS SLE

TOYOTA NOAH HYBRID  
 1/11/2019  
 SMP5728M(AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper			
2	10 pcs	Rear bumper clips	1,583.20		
3	2 pcs	Rear bumper screw		30.00	20
4	2 pcs	Rear bumper o/s & n/s reflector SVC		30.00	20
5	2 pcs	Rear bumper o/s & n/s retainer SVC	247.10		
6	1 set	Rear bumper reverse sensor	208.60		
7	1 pc	Rear bumper tow cover	956.20		
8	2 pcs	Rear bumper o/s & n/s top garnish	70.50		
9	8 pc	Rear bumper o/s & n/s top garnish clips	561.80		
10	1 pc	Rear tail gate		24.00	12
11	1 pc	Rear tail gate inner trim	2434.50		
12	8 pcs	Rear tail gate inner trim clips	725.80		
13	1 pc	Rear HYBRID emblem	32.00	SN	20
14	1 pc	Rear tail gate emblem	88.20		
15	1 pc	Rear tail gate moulding chrome	121.20		
16	1 pc	Rear tail gate lock upper	856.50		
17	1 pc	Rear tail gate lock actuator	251.70		
18	1 pc	Rear tail gate weather strip	765.30		
19	1 pc	Rear end panel	424.00		
20	1 pc	Rear end panel inner trim	645.20		
21	6 pcs	Rear end panel inner trim clips	292.50		
22	2 pcs	Rear o/s & n/s fender inner trim		30.00	20
23	1 pc	Rear boot floor panel	1,765.20		
24	2 pcs	Rear o/s & n/s tail lamp panel			
25	2 pcs	Rear o/s & n/s tail lamp			
26	1 pc	Rear windscreen moulding	1,635.60		
27	1 pc	Rear windscreen sealant		220.00	100
28	1 pc	Solar film		120.00	60
Sub Total:			13,665.10	654.00	0.00
After Less %:			25%	0%	10%
Labour			10,248.83	654.00	0.00
1		To dismantle damaged parts, straighten & welding.			
2		To spray painting.	1,400.00		
3		To remove and refit rear windscreen	1,200.00		
4		To remove and replace rear reverse sensor.	200.00		
5		To remove and refit mechanism & motor	80.00		
6		To remove and refit upholstery to facilitate repair	80.00		
7		To remove and replace rear tail gate	180.00		
8		To re seal anti rust.	180.00		
9		To re set electrical system.	100.00		
10		To check wiring.	250.00		
Sub Total:			3,720.00		
Total:			14,622.83		
After Less 20%:			11,698.26		

DT 1025  
 nec  
 nec  
 Cra 123.5  
 nec 100  
 cut 200  
 SVC  
 DIS 360  
 nec  
 DT 1416.35  
 - Cut 445.8  
 nec  
 nec 67.6  
 - cut - 273.8  
 jam  
 XNW  
 - cut 299.2  
 - DT 590  
 - cut/BT 149  
 nec  
 BT - 681  
 XR  
 - bt 390  
 - sec 1562.  
 nec  
 nec  
 SVC  
 1600  
 120  
 20  
 80  
 30  
 30  
 60  
 40  
 30  
 20  
 8000

Chan San Choon  
 Director  
 DipEng, AAE MIMI, MSAE(Aust)



biSAFE 8778 1999



# Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

## SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : SMQ2070R

Accident Date : 14/1/2021

Model: TOYOTA NOAH HYBRID  
1/11/2019

Location : CTE TOWARDS SLE BEFORE ANG MO KIO AVE 1

3P: SMP5728M(AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear carpet			
2	1 pc	Rear carpet cover	810.50		
3	1 pc	Rear antenna	81.6		
4	1 pc	Rear o/s fender inner trim holder bracket	221.6		
5	1 pc	Rear floor board	45.60		
6	1 pc	Rear blower	710.70		
			1,851.60		
		Sub Total:	3,721.60	0.00	0.00
			25%	0%	10%
		After Less %:	2,791.20	0.00	0.00
		Total:		2,791.20	
		After Less 20%:		2,232.96	

✓ Cat 350  
✓ DT  
✓ Cat 165  
✓ C/A  
✓ BT  
X SUC

*Chan*

Chan San Choon  
Director  
DipEng, AAE MIMI, MSAE(Aust)



8778 1999  
24 hr accident call

