

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

**Estimate**

38 Woodlands Industrial Park E1  
 #05-18, Singapore 757700  
 Tel: 64688834 Fax: 64622278  
 E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2201-030  
 DATE : 17-Jan-2021  
 POLICY NO. : FWD PNPV2020-00008510  
 VEHICLE REG. NO. : SLS7740J  
 VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS AT

TO Motor Claim Department  
**China Taiping Insurance (Singapore) Pte. Ltd**  
 3 Anson Road, #15-00 Springleaf Tower  
 Singapore 079909  
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<b><u>SPARE PARTS</u></b>			
1	Front Bumper	1	\$ 780.00	\$ 780.00
2	Front Bumper Clip	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH	1	\$ 50.00	\$ 50.00
4	Front Headlamp RH	1	\$ 1,080.00	\$ 1,080.00
5	Front Headlamp Bracket RH	1	\$ 40.00	\$ 40.00
6	Front Fender Clip	10	\$ 5.00	\$ 50.00
7	Front Foglamp RH	1	\$ 280.00	\$ 280.00
8	Front Foglamp Garnish RH	1	\$ 120.00	\$ 120.00
<b>Total Spare Parts</b>				\$ 2,450.00
	<b><u>SPECIAL NETT</u></b>			
<b>Total Special Nett</b>				\$ -
	<b><u>LABOUR</u></b>			
9	Spray Painting Whole Front Bumper, Bonnet and Fender RH	1	\$ 700.00	\$ 700.00
10	Remove, Refit and Repair Affected Accident Parts	1	\$ 500.00	\$ 500.00
11	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

<b>Total Labour</b>	\$ 1,230.00
<b>Amount Before Excess</b>	\$ 3,680.00
<b>Add GST @ 7%</b>	257.60
<b>Total Amount Payable</b>	\$ 3,937.60