

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS4/CTI22000578/EVY3E2

Date: 09/03/2022

REFERENCE

Insured/Claimant: JUNAIDAH BTE ABDULLAH Policy No: DMPCSNW00262992100

Date of Loss: 23/12/2021

Nature of Claim: OD

Claim No: SNM22D200155/C01/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT48A	Engine No:	1AZH321803
Make & Model:	TOYOTA PICNIC, 2.0 (A)	Chassis No:	JTEGH23B200026417
Reg. Date:	09/03/2009 (Man. Year: 2009)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50.00	0.00	50.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50.00	0.00	50.00	100.00
- Excess (S\$)	0.00	1,850.00	-1,850.00	
(S\$)	50.00	-1,850.00	1,900.00	3,800.00
+ GST 7.00/0.00% (S\$)	3.50	0.00	3.50	100.00
Nett Amount (S\$)	53.50	-1,850.00	1,903.50	3,557.94

INSPECTION

Date of Assignment:	14/01/2022	Present Location:	Goldbell Engineering Pte Ltd (Tuas)
Date Inspected:	17/01/2022	Inspected At:	Goldbell Engineering Pte Ltd (Tuas)
			10 Tuas Ave 18
			Singapore 638894
Estimated Period of Repair:	0.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$50,000.00
OMV :	\$23,511.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$31,933.00
COE Rebate (2) :	\$22,828.00
Total Rebate (1) + (2) = :	\$22,828.00

The total amount incurred will be Market Value \$50,000.00 minus Total Rebate \$22,828.00 = \$27,172.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Mar 2022)
Parts:	M1-MPV	TOYOTA PICNIC 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT48A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RECOMMENDED TOTAL LOSS		50.00 F	*- F
F=Franchise part.						
				Total Parts (\$)	50.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >