

VENTURES AUTO PTE LTD

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 202143430K

TPAXA
Xiao Tony

Make/ Model : LEXUS RX200

Date: 07.01.2022

Chassis No : JTJBAMCA202023900

Vehicle No: SMW3636X

Date/Time of Accid: 09.09.2021/2120

Reg date : 27.04.2017

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	FRT BUMPER <i>Rehnd</i>	1	\$ 1,726.92	\$ 1,726.92
2	FRT FOG LAMP BRACKET RH <i>Rehnd</i>	1	\$ 297.84	\$ 297.84
3	FRT BUMPER TOW COVER RH <i>Rehnd</i>	1	\$ 106.08	\$ 106.08
4	FRT FOG LAMP COVER RH <i>Rehnd</i>	1	\$ 118.44	\$ 118.44
5	FRT FOG LAMP COVER CHROME MLDG RH <i>Rehnd</i>	1	\$ 235.56	\$ 235.56
6	FRT FOG LAMP COVER ARM RH <i>Rehnd</i>	1	\$ 162.12	\$ 162.12
7	FRT BUMPER SIDE RETAINER RH <i>Rehnd</i>	1	\$ 142.68	\$ 142.68
8	FRT BUMPER SPONGE	1	\$ 133.56	\$ 133.56
9	FRT BUMPER REINFORCEMENT	1	\$ 866.52	\$ 866.52
10	FRT BUMPER UNDER DUST COVER	1	\$ 180.60	\$ 180.60
11	FRT BUMPER LOW LIP RH <i>Rehnd</i>	1	\$ 150.72	\$ 150.72
12	FRT BUMPER LOW LIP CENTRE <i>Rehnd</i>	1	\$ 173.16	\$ 173.16
13	FRT GRILLE CHROME MLDG UPP <i>Rehnd</i>	1	\$ 582.36	\$ 582.36
14	FRT GRILLE CHROME MLDG LOW <i>Rehnd</i>	1	\$ 1,080.00	\$ 1,080.00
15	FRT GRILLE UPP <i>Rehnd</i>	1	\$ 1,560.24	\$ 1,560.24
16	FRT GRILLE LOW <i>Rehnd</i>	1	\$ 374.64	\$ 374.64
17	FRT GRILLE TOP SEAL <i>Rehnd</i>	1	\$ 55.56	\$ 55.56
18	FRT BONNET <i>Rehnd</i>	1	\$ 3,213.36	\$ 3,213.36
19	FRT FENDER RH <i>Rehnd</i>	1	\$ 1,085.88	\$ 1,085.88
20	FRT FENDER INNERSHIELD RH <i>Rehnd</i>	1	\$ 539.64	\$ 539.64
21	FRT FENDER PROTECTOR RH <i>Rehnd</i>	1	\$ 256.80	\$ 256.80
22	FRT RADIATOR AIR GUIDE UPP RH <i>Rehnd</i>	1	\$ 117.84	\$ 117.84
23	FRT RADIATOR AIR GUIDE LOW RH <i>Rehnd</i>	1	\$ 83.52	\$ 83.52
24	FRT HEADLAMP RH <i>Rehnd</i>	1	\$ 8,551.62	\$ 8,551.62
25	FRT HEADLAMP CONTROL UNIT RH <i>Rehnd</i>	1	\$ 1,045.92	\$ 1,045.92
26	FRT FOGLAMP RH <i>Rehnd</i>	1	\$ 298.68	\$ 298.68
27	FRT CORNERING LAMP RH <i>Rehnd</i>	1	\$ 1,258.20	\$ 1,258.20
28	FRT PARKING SENSOR CENTRE <i>Rehnd</i>	1	\$ 362.88	\$ 362.88
29	FRT PARKING SENSOR SIDE <i>Rehnd</i>	1	\$ 362.88	\$ 362.88
30	FRT PARKING SENSOR HOLDER <i>Rehnd</i>	1	\$ 380.40	\$ 380.40
31	FRT WIPER WASHER TANK <i>Rehnd</i>	1	\$ 254.52	\$ 254.52
32	FRT WIPER WASHER TANK NECK <i>Rehnd</i>	1	\$ 95.76	\$ 95.76
33	FRT HEADLAMP WASHER COVER RH <i>Rehnd</i>	1	\$ 81.84	\$ 81.84
34	FRT HEADLAMP WASHER BRACKET RH <i>Rehnd</i>	1	\$ 106.08	\$ 106.08
35	FRT HEADLAMP WASHER NOZZLE ACTUATOR RH <i>Rehnd</i>	1	\$ 653.88	\$ 653.88

Total List Price Cost

\$ 26,696.70

PARTS DISCOUNT 10% \$ 24,027.03

1095068
985561

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
--------------	-------------------	-----	----------	----------------

1	FRT BUMPER CLIP	10	\$6.00	\$60.00
2	FRT GRILLE CLIP	10	\$6.00	\$60.00
3	FRT FENDER INNERSHIELD CLIP	10	\$6.00	\$60.00
4	FRT FENDER PROTECTOR CLIP	10	\$6.00	\$60.00
5	RADIATOR COOLANT	1	\$100.00	\$100.00
6	FRT NUMBER PLATE	1	\$65.00	\$65.00
Total Special Nett Items			\$	405.00
60				
Labour Works/ Panel Beating Related Works				
Job Scope			Quotation	
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN ,STRAIGHTENED MEMBER			\$ 1,400.00	
Spray Painting				
Job Scope			Quotation	
TO RESPRAY AFFECTED AREAS			\$ 1,400.00	
Others Cost (Accident Repair Related Expenses)				
Job Scope			Quotation	
To disconnect front wire harness of electrical component to facilitate repairs,reconnect and check electrical function after repair			\$ 120.00	
To charge up ac gas			\$ 300.00	
To remove & refit radiator and perform pressure test			\$ 120.00	
To perform reset of faulty code			\$ 350.00	
To remove & refit front parking sensor and conduct test			\$ 100.00	
To perform ADAS reset			\$ 600.00	
Total Others Cost			\$ 1,590.00	
GRAND TOTAL			\$ 28,822.03	

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
1/5 18/07/22

04 days.

total 11055.61
1/5: 8.8K.

8.8K.