

VENTURES AUTO PTE LTD

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 202143430K

Make/ Model : LEXUS RX200

Date: 07.01.2022

Chassis No : JTJBAMCA202023900

Vehicle No: SMW3636X

Date Time of Accid: 09.09.2021/2120

Reg date : 27.04.2017

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	FRT BUMPER <i>Ret-rt</i>	1	\$ 1,726.92	\$ 1,726.92
2	FRT FOG LAMP BRACKET RH	1	\$ 297.84	\$ 297.84
3	FRT BUMPER TOW COVER RH <i>new</i>	1	\$ 106.08	\$ 106.08
4	FRT FOG LAMP COVER RH <i>lit</i>	1	\$ 118.44	\$ 118.44
5	FRT FOG LAMP COVER CHROME MLDG RH <i>new</i>	1	\$ 235.56	\$ 235.56
6	FRT FOG LAMP COVER ARM RH <i>lit</i>	1	\$ 162.12	\$ 162.12
7	FRT BUMPER SIDE RETAINER RH <i>new</i>	1	\$ 142.68	\$ 142.68
8	FRT BUMPER SPONGE	1	\$ 133.56	\$ 133.56
9	FRT BUMPER REINFORCEMENT <i>2 pt</i>	1	\$ 866.52	\$ 866.52
10	FRT BUMPER UNDER DUST COVER <i>1 m</i>	1	\$ 180.60	\$ 180.60
11	FRT BUMPER LOW LIP RH <i>lit</i>	1	\$ 150.72	\$ 150.72
12	FRT BUMPER LOW LIP CENTRE <i>new</i>	1	\$ 173.16	\$ 173.16
13	FRT GRILLE CHROME MLDG UPP <i>2 pt</i>	1	\$ 582.36	\$ 582.36
14	FRT GRILLE CHROME MLDG LOW <i>2 pt</i>	1	\$ 1,080.00	\$ 1,080.00
15	FRT GRILLE UPP <i>2 pt</i>	1	\$ 1,560.24	\$ 1,560.24
16	FRT GRILLE LOW <i>2 pt</i>	1	\$ 374.64	\$ 374.64
17	FRT GRILLE TOP SEAL <i>1 m</i>	1	\$ 55.56	\$ 55.56
18	FRT BONNET <i>new</i>	1	\$ 3,213.36	\$ 3,213.36
19	FRT FENDER RH	1	\$ 1,085.88	\$ 1,085.88
20	FRT FENDER INNERSHIELD RH <i>new</i>	1	\$ 539.64	\$ 539.64
21	FRT FENDER PROTECTOR RH <i>lit</i>	1	\$ 256.80	\$ 256.80
22	FRT RADIATOR AIR GUIDE UPP RH <i>2 pt</i>	1	\$ 117.84	\$ 117.84
23	FRT RADIATOR AIR GUIDE LOW RH <i>2 pt</i>	1	\$ 83.52	\$ 83.52
24	FRT HEADLAMP RH ?	1	\$ 8,551.62	\$ 8,551.62
25	FRT HEADLAMP CONTROL UNIT RH <i>new</i>	1	\$ 1,045.92	\$ 1,045.92
26	FRT FOGLAMP RH ?	1	\$ 298.68	\$ 298.68
27	FRT CORNERING LAMP RH <i>new</i>	1	\$ 1,258.20	\$ 1,258.20
28	FRT PARKING SENSOR CENTRE <i>new</i>	1	\$ 362.88	\$ 362.88
29	FRT PARKING SENSOR SIDE	1	\$ 362.88	\$ 362.88
30	FRT PARKING SENSOR HOLDER ?	1	\$ 380.40	\$ 380.40
31	FRT WIPER WASHER TANK	1	\$ 254.52	\$ 254.52
32	FRT WIPER WASHER TANK NECK <i>new</i>	1	\$ 95.76	\$ 95.76
33	FRT HEADLAMP WASHER COVER RH <i>2 pt</i>	1	\$ 81.84	\$ 81.84
34	FRT HEADLAMP WASHER BRACKET RH <i>1 m</i>	1	\$ 106.08	\$ 106.08
35	FRT HEADLAMP WASHER NOZZLE ACTUATOR RH	1	\$ 653.88	\$ 653.88

Total List Price Cost

\$ 26,696.70

PARTS DISCOUNT 10%

\$ 24,027.03

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
--------------	-------------------	-----	----------	----------------

1	FRT BUMPER CLIP <i>New</i>	10	\$6.00	\$60.00
2	FRT GRILLE CLIP <i>New</i>	10	\$6.00	\$60.00
3	FRT FENDER INNERSHIELD CLIP <i>New</i>	10	\$6.00	\$60.00
4	FRT FENDER PROTECTOR CLIP <i>New</i>	10	\$6.00	\$60.00
5	RADIATOR COOLANT <i>New</i>	1	\$100.00	\$100.00
6	FRT NUMBER PLATE <i>New</i>	1	\$65.00	\$65.00
Total Special Nett Items			\$	405.00

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN, STRAIGHTENED MEMBER	\$ 1,400.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,400.00

Others Cost (Accident Repair Related Expenses)

Others Cost (Accident Repair Related Expenses)		Quotation	
Job Scope			
To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair		\$	120.00
To charge up ac gas		\$	300.00
To remove & refit radiator and perform pressure test		\$	120.00
To perform reset of faulty code		\$	350.00
To remove & refit front parking sensor and conduct test		\$	100.00
To perform ADAS reset		\$	600.00
Total Others Cost		\$	1,590.00
GRAND TOTAL		\$	28,822.03

Adnan Lij
1/5/18/01/22

04 days