

BIFROST AUTO PTE LTD
8 KAKI BUKIT AVE 4 #01-49
SINGAPORE 415875
TEL: 64524457 FAX: 64524584
ATT: IKHWAN HP 93290237

Estimate for SKB8387R(Hyundai Avante)

1 *FRONT HEAD LAMP RH	✓	\$455.00	BRV
1 *FRONT HEAD LAMP LOWER BRACKET RH	✓	\$67.20	BRV
1 *FRONT SUPPORT PANEL	783 ✓	\$928.90	BR
1 *FRONT GRILLE	✓	\$245.00	CRA
1 *FRONT GRILLE EMBLEM	✓	\$37.50	NEC
1 *FRONT BUMPER	494 ✓	\$530.20	DD ✓
2 *FRONT BUMPER SIDE RETAINER	✓	\$76.80	NECV
1 *FRONT BUMPER INNER SPONGE	✓	\$144.90	? BR
1 *FRONT SHOCK ABSORBER RH	×	\$450.00	} ? NN
1 *FRONT SHOCK ABSORBER MOUNTING RH	×	\$344.00	
1 *FRONT KNUCKLE ARM RH	×	\$504.40	
1 *FRONT WHEEL BEARING RH	×	\$269.60	
1 *FRONT WHEEL BEARING HUB RH	×	\$390.60	
1 *FRONT LOWER ARM RH	×	\$496.60	} ? NN
1 *FRONT BALL JOINT	×	\$165.00	
1 *FRONT FENDER RH	525 ✓	\$650.30	DD ✓
1 *FRONT FENDER INNER SHIELD RH	✓	\$172.00	? TN
		\$5,928.00	3000.40
		\$1,185.60	-20%
		\$4,742.40	2400.32

Less 20%

S/Nett

*FRONT RIM RH	local repair	200.00 ✓	\$700.00	ATXR
*FRONT TYRE RH			nn X \$350.00	
*FRONT BUMPER CLIP		30.00 ✓	\$50.00	NECV
*FRONT FENDER INNER SHIELD CLIP		20 ✓	\$100.00	? nec
			\$1,200.00	250

TOWING CHARGE	\$120.00	NNX
REMOVE AND RENEW AIRCON CONDENSER AND REFILL GAS	\$150.00	? 80
CHECK WHEEL ALIGNMENT	\$80.00	✓
LABOUR CHARGE STRAIGHTEN REPAIR FRONT DAMAGE PORTION, CUT, WELDING	\$1,500.00	1000
RESPRAYING PAINTING	\$1,000.00	600
TUFF KOTE	\$100.00	NNX

Total

4410.32

L/S - 3528.25
= 3550

\$2,950.00

\$8,892.40

1760

Survey
17/1/2022
Tatin Lin
1300hrs
Lump sum repair
Repair days 7