



# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636  
Tel: 6559 8944 / Fax: 6269 2404

**China Taiping Insurance (S) Pte Ltd**  
3 Anson Rd, #16-00  
Springleaf Tower  
Singapore (079909)  
ATTN: MOTOR CLAIM DEPARTMENT

*Not Withdrawn  
11/12/21  
Penny After Pain*

DEAR SIR / MADAM :

**ACCIDENT REPAIR ON: SKC9583A**

Date: 27/12/2021

MODEL : CR-Z HYBRID 1.5 A

Page : 1 of 2

POLICY NO :

CHASSIS NO : ZF11004081

YEAR OF MANUFACTURE : 2011

DATE / TIME OF ACCIDENT: 06/01/2022 Time: 1125Hrs AT 279 COMPASSVALE ANCILLIA

THIRD PARTY VEHICLE NO: SLM2086D

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

**Replacement Of Parts**

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Front Head Light RH	1	\$ 1,205.00	Car	\$ 1,205.00 ✓
2 Front Grille	1	\$ 225.70	Pa	\$ 225.70 X
3 Head Light Retainers RH	1	\$ 35.00	Dis	\$ 35.00 ✓
4 Front Bumper	1	\$ 770.50	urgent	\$ 770.50 ✓
5 Front Bumper Retainers	1	\$ 18.00	Pa	\$ 18.00 X
6 Front Fender RH	1	\$ 580.00	R	\$ 580.00 X
7 Honda Emblem	1	\$ 27.50	R	\$ 27.50 ✓
8 Front Side Fender Cowling RH	1	\$ 116.60	CM	\$ 116.60 ✓
9 Front Bumper Bottom Lid RH	1	\$ 21.40	Pa	\$ 21.40 X
10 Front Absorber RH	1	\$ 367.60	Pa	\$ 367.60 X
11 Lower Arm RH	1	\$ 608.40	Pa	\$ 608.40 X
12 Front Rim RH	CR 1	\$ 960.80	scr	\$ 960.80 150.00
13 Dry Shaft RH	1	\$ 1,338.50	R	\$ 1,338.50 X
14 Stabilizing Link RH	1	\$ 81.90	Pa	\$ 81.90 X
15 Wheel Bearing RH	1	\$ 131.80		\$ 131.80 7
16 Support Panel	1	\$ 689.50	R	\$ 689.50 X
17 Bonnet	1	\$ 872.10	R	\$ 872.10 X
18 Front Reinforcement Bar	1	\$ 249.40	R	\$ 249.40 X
19 Tie Rod RH	1	\$ 90.30	Pa	\$ 90.30 X
20 Tie Rod End RH	1	\$ 144.50	Pa	\$ 144.50 X

21	Top Stopper RH	1	\$ 25.90	<i>h</i>	\$ 25.90	X
22	Dust Cover Rh	1	\$ 27.40	<i>h</i>	\$ 27.40	X
23	Bush RH	1	\$ 43.90	<i>h</i>	\$ 43.90	X

Sub-Total: 8,631.70  
 Less: 20% discount - 1,726.34  
**Total Parts after 20% discount: 6,905.36**

**Special Nett Items**

1	Anti-rust coating	4	80.00	<i>h</i>	320.00	X
2	Front Tyre RH	1	285.00	<i>h</i>	285.00	X
					<u>605.00</u>	

**Total Parts: 7,510.36**

**Labour Charges For Front Portion**

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	2,000.00	<i>400l</i>
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	2,000.00	<i>400l</i>
3	Provide skill labour to disconnect and check electrical wiring	150.00	<i>20l</i>
4	Provide Labour skill to check undercarriage, removal and replacement	300.00	<i>?</i>
5	Provide skill labour for wheel alignment	200.00	<i>60l</i>

<b>Total Labour:</b>	<b>4,650.00</b>
<b>Total Parts &amp; Labour:</b>	<b>12,160.36</b>
<b>GST 7%</b>	<b>851.23</b>
<b>Grand Total:</b>	<b>13,011.59</b>

**Estimate Repair Duration** 45 days

*4 days*

ACCIDENT VEHICLE OF : SKC9583A

Page : 2 of 2

**Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature  
 Date

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 07/01/2022 15:28 (SGT)  
Date of Accident ..... 06/01/2022 11:25 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... 279 COMPASSVALE ANCILLIA  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SKC9853A

INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... LIM SENG YIONG AARON  
NRIC No ..... S8201080G  
Email Address ..... LIMS.Y.AARON@GMAIL.COM  
Mobile Phone No ..... (Phone) +65-93689682  
Alternative Phone No ..... +65-93689682

## VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Cr-z  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1500

## INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 5123517505  
Cover Note Number ..... -

## DRIVER

Name of Driver ..... LIM SENG YIONG AARON  
NRIC No ..... S8201080G

