

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

China Taiping Insurance (S) Pte Ltd

3 Anson Rd, #16-00

Springleaf Tower

Singapore (079909)

ATTN: MOTOR CLAIM DEPARTMENT

*Not Withdraw
61 Day @ 2050/-
Recovery After Pains
4 days*

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SKC9583A

MODEL : CR-Z HYBRID 1.5 A

POLICY NO :

CHASSIS NO : ZF11004081

YEAR OF MANUFACTURE : 2011

DATE / TIME OF ACCIDENT: 06/01/2022 Time: 1125Hrs AT 279 COMPASSVALE ANCILLIA

THIRD PARTY VEHICLE NO: SLM2086D

Date: 27/12/2021

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Front Head Light RH <i>1081</i>	1	\$ 1,205.00	<i>CR</i>	\$ 1,205.00 ✓
2 Front Grille	1	\$ 225.70	<i>PR</i>	\$ 225.70 X
3 Head Light Retainers RH	1	\$ 35.00	<i>DIS</i>	\$ 35.00 ✓
4 Front Bumper <i>680.20</i>	1	\$ 770.50	<i>RECENT</i>	\$ 770.50 ✓
5 Front Bumper Retainers	1	\$ 18.00	<i>PR</i>	\$ 18.00 X
6 Front Fender RH	1	\$ 580.00	<i>R</i>	\$ 580.00 X
7 Honda Emblem	1	\$ 27.50	<i>NR</i>	\$ 27.50 ✓
8 Front Side Fender Cowling RH	1	\$ 116.60	<i>CR</i>	\$ 116.60 ✓
9 Front Bumper Bottom Lid RH	1	\$ 21.40	<i>PR</i>	\$ 21.40 X
10 Front Absorber RH	1	\$ 367.60	<i>PR</i>	\$ 367.60 X
11 Lower Arm RH	1	\$ 608.40	<i>PR</i>	\$ 608.40 X
12 Front Rim RH	<i>CR</i> 1	\$ 960.80	<i>PR</i>	\$ 960.80 <i>1500</i>
13 Dry Shaft RH	1	\$ 1,338.50	<i>R</i>	\$ 1,338.50 X
14 Stablizing Link RH	1	\$ 81.90	<i>PR</i>	\$ 81.90 X
15 Wheel Bearing RH	1	\$ 131.80	<i>NR</i>	\$ 131.80 X
16 Support Panel	1	\$ 689.50	<i>R</i>	\$ 689.50 X
17 Bonnet	1	\$ 872.10	<i>R</i>	\$ 872.10 X
18 Front Reinforment Bar	1	\$ 249.40	<i>R</i>	\$ 249.40 X
19 Tie Rod RH	1	\$ 90.30	<i>PR</i>	\$ 90.30 X
20 Tie Rod End RH	1	\$ 144.50	<i>PR</i>	\$ 144.50 X

21	Top Stopper RH	1	\$ 25.90	<i>ln</i>	\$ 25.90	X
22	Dust Cover Rh	1	\$ 27.40	<i>ln</i>	\$ 27.40	X
23	Bush RH	1	\$ 43.90	<i>ln</i>	\$ 43.90	X

Sub-Total: 8,631.70
 Less: 20% discount - 1,726.34
Total Parts after 20% discount: 6,905.36

Special Nett Items

1	Anti-rust coating	4	80.00	<i>ln</i>	320.00	X
2	Front Tyre RH	1	285.00	<i>ln</i>	285.00	X
					605.00	

Total Parts: 7,510.36

Labour Charges For Front Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.		2,000.00		<i>400l</i>
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities		2,000.00		<i>400l</i>
3	Provide skill labour to disconnect and check electrical wiring		150.00		<i>20l</i>
4	Provide Labour skill to check undercarriage, removal and replacement		300.00	<i>ln</i>	<i>X</i>
5	Provide skill labour for wheel alignment		200.00		<i>60l</i>

Total Labour:	4,650.00
Total Parts & Labour:	12,160.36
GST 7%	851.23
Grand Total:	13,011.59

Estimate Repair Duration 45 days

4 days

ACCIDENT VEHICLE OF : **SKC9583A**

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

ESTIMATOR: *NINJA LO*

Survey attended by:

Name : _____
Company : _____
Date : _____
Time : _____
Contact No : _____
Email : _____