

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000583/KNY3Q2**Date:** 30/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00064762100	
Claimant Vehicle No :	FBH7331H	Insured Vehicle No :	GBL3411R	
Date of Loss:	30/11/2021	Nature of Claim:	TP	Claim No: SNM21D206926/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH7331H		Engine No:	E3J2E008837
Make & Model:	YAMAHA YBR125, 124cc (M)		Chassis No:	LBPKE1782D0014326
Reg. Date:	11/09/2013 (Man. Year: 2013)		Odometer:	40000 km
Colour:	Metallic Blue			
Engine Capacity:	124 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90 R18	Rear Tyre Size:	3.60 R81
Front Left Side:	Golden Boy 6 mm	Rear Left Side:	Shinko 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,903.60	2,492.57	3,411.03	57.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	280.00	1,080.00	79.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,263.60	2,772.57	4,491.03	61.83
Approved Total (Overridden) (\$\$)		2,000.00		
(\$\$)	7,263.60	2,000.00	5,263.60	72.47
+ GST 7.00/7.00% (\$\$)	508.45	140.00	368.45	72.47
Nett Amount (\$\$)	7,772.05	2,140.00	5,632.05	72.47

INSPECTION

Date of Assignment:	17/01/2022	
Date Inspected:	17/01/2022 Inspected At:	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Aug 2022)	
Parts:	N/A	YAMAHA YBR125 124cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH7331H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE LEVER	Serviceable	68.00 F	*- FL
2	1		*CLUTCH LEVER	Serviceable	68.00 F	*- FL
3	1		*GEAR PEDAL	Repair	90.20 F	*- FL
4	1		*FORK OIL SEAL -LH	Necessary	38.00 F	*38.00 FL
5	1		*FORK OIL SEAL -RH	Necessary	38.00 F	*38.00 FL
6	1		*FRONT FAIRING -LH	Serviceable	288.00 F	*- FL
7	1		*FRONT FAIRING -RH	Serviceable	288.00 F	*- FL
8	1		*FRONT FORK -LH	Bent	386.00 F	*252.00 FL
9	1		*FRONT FORK -RH	Bent	386.00 F	*252.00 FL
10	1		*FRONT FORK TUBE-LH	Bent	222.00 F	*222.00 FL
11	1		*FRONT FORK TUBE-RH	Bent	222.00 F	*222.00 FL
12	1		*FRONT WHEEL BEARING	Not Necessary	28.00 F	*- FL
13	1		*FRONT WHEEL RIM FENDER	Serviceable	198.00 F	*- FL
14	1		*FRONT HANDLE BAR HOLDER BEARING -TOP	Serviceable	85.00 F	*- FL
15	1		*FRONT HANDLE BAR HOLDER BEARING -LOWER	Serviceable	85.00 F	*- FL
16	1		*FRONT HANDLE BAR	Bent	105.20 F	*105.20 FL
17	1		*FRONT SIGNAL LAMP -LH	Broken	125.10 F	*125.10 FL
18	1		*FRONT HEADLAMP COVER -CENTRE	Missing	288.00 F	*288.00 FL
19	1		*LOWER STEP BAR	Repair	105.10 F	*- FL
20	1		*FRONT FORK HOLDER BRACKET	Distorted	380.00 F	*380.00 FL
21	1		*FRONT COWLING -LH	Broken	165.00 F	*165.00 FL
22	1		*HANDLE RUBBER -LH	Serviceable	38.00 F	*- FL
23	1		*HANDLE RUBBER -RH	Serviceable	38.00 F	*- FL
24	1		*FRONT COWLING -RH	Serviceable	165.00 F	*- FL
25	1		*FRONT WHEEL BEARING	Not Necessary	45.00 F	*- FL
26	1		*HEAD LAMP	Missing	480.00 F	*480.00 FL
27	1		*SPEED METER	Serviceable	785.00 F	*- FL
28	1		*SIDE STAND RUBBER -LH	Serviceable	65.00 F	*- FL
29	1		*SIDE STAND RUBBER -RH	Serviceable	65.00 F	*- FL
30	1		*WING MIRROR -LH	Serviceable	144.00 F	*- FL
31	1		*HANDLE BAR BRACKET	Bent	180.00 F	*180.00 FL
32	1		*REAR BOX	Serviceable	195.00 F	*- FL
33	1		*FRONT NUMBER PLATE	Missing	45.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,903.60	2,767.30
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	274.73
Total Parts (\$)	5,903.60	2,492.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS PANEL BEAT WHERE NECESSARY	New	500.00	150.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	500.00	0.00
3	TO ALIGN MAIN BODY FRAME	New	300.00	100.00
4	TO TOW VEHICLE TO WORKSHOP	New	60.00	30.00
Gross Labour Cost (S\$)			1,360.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >