



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S: China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 30/11/2021
TP Veh Reg No: GBL3411R

Estimate No: ES2100123
Date: 17 Jan 2022
Policy No:
Veh Reg No: FBH7331H
Make/Model: YAMAHA YBR 125
MANUAL
Chassis No: LBPKE1782D0014326
Engine No: E3J2E008837
Reg. Date: 11/09/2013

Estimate Repair Cost to Vehicle No :FBH7331H

Description	U/Price	Quantity	List Price	Amount
Net Price			SS	SS
1 FRONT NUMBER PLATE	45.00	1 PC	45.00	45.00
Spare Parts				
2 BRAKE LEVER	68.00	1 PC	68.00	X
3 CLUTCH LEVER	68.00	1 PC	68.00	X
4 GEAR PEDAL	90.20	1 PC	90.20	X
5 FORK OIL SEAL - LH	38.00	1 PC	38.00	—
6 FORK OIL SEAL - RH	38.00	1 PC	38.00	—
7 FRONT FAIRING - LH	288.00	1 PC	288.00	X
8 FRONT FAIRING - RH	288.00	1 PC	288.00	X
9 FRONT FORK - LH	386.00	1 PC	386.00	—
10 FRONT FORK - RH	386.00	1 PC	386.00	—
11 FRONT FORK TUBE - LH	222.00	1 PC	222.00	—
12 FRONT FORK TUBE - RH	222.00	1 PC	222.00	—
13 FRONT WHEEL BEARING	28.00	1 PC	28.00	X
14 FRONT WHEEL RIM FENDER	198.00	1 PC	198.00	X
15 FRONT HANDLE BAR HOLDER BEARING - TOP	85.00	1 PC	85.00	X
16 FRONT HANDLE BAR HOLDER BEARING - LOWER	85.00	1 PC	85.00	X
17 FRONT HANDLE BAR	105.20	1 PC	105.20	—
18 FRONT SIGNAL LAMP - LH	125.10	1 PC	125.10	—
19 FRONT HEADLAMP COVER - CENTRE	288.00	1 PC	288.00	—
20 LOWER STEP BAR	105.10	1 PC	105.10	X
21 FRONT FORK HOLDER BRACKER	380.00	1 PC	380.00	—
22 FRONT COWLING - LH	165.00	1 PC	165.00	—
23 HANDLE RUBBER - LH	38.00	1 PC	38.00	X
24 HANDLE RUBBER - RH	38.00	1 PC	38.00	X
25 FRONT COWLING - RH	165.00	1 PC	165.00	X
26 FRONT WHEEL BEARING	45.00	1 PC	45.00	X
27 HEAD LAMP	480.00	1 PC	480.00	—
28 SPEED METER	785.00	1 PC	785.00	X
29 SIDE STAND RUBBER - LH	65.00	1 PC	65.00	X
30 SIDE STAND RUBBER - RH	65.00	1 PC	65.00	X
31 WING MIRROR - LH	144.00	1 PC	144.00	X
32 HANDLE BAR BRACKET	180.00	1 PC	180.00	—
33 REAR BOX	195.00	1 PC	195.00	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 30/11/2021
TP Veh Reg No: GBL3411R

Estimate No: ES2100123
Date: 17 Jan 2022
Policy No:
Veh Reg No: FBH7331H
Make/Model: YAMAHA YBR 125
MANUAL
Chassis No: LBPKE1782D0014326
Engine No: E3J2E008837
Reg. Date: 11/09/2013

Estimate Repair Cost to Vehicle No :FBH7331H

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			5,858.60	5,858.60
Labour				
34 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	500.00	1 JOB	500.00	1501
35 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	500.00	1 JOB	500.00	X
36 TO ALIGN MAIN BODY FRAME.	300.00	1 JOB	300.00	1001
37 TO TOW VEHICLE TO WORKSHOP.	60.00	1 JOB	60.00	301
			1,360.00	1,360.00
			Total	SS 7,263.60
			Add GST @ 7%	508.45
			Total Amount Payable	SS 7,772.05

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED SEVENTY TWO AND CENTS FIVE ONLY

For Yee Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE