

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22000584/EVY3E2**Date:** 28/03/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP310905
Claimant Vehicle No :	FBQ1580Y	Insured Vehicle No :	SCV6655U
Date of Loss:	10/03/2020	Nature of Claim:	TP
		Claim No:	MPC01811

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ1580Y	Engine No:	G3H6E0015370
Make & Model:	YAMAHA NMAX155, 155cc ABS	Chassis No:	MH3SG431000012376
Reg. Date:	06/08/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Grey		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60 R13	Rear Tyre Size:	140/60 R13
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/01/2022	
Date Inspected:	17/01/2022	Inspected At: Ah Fook Motor (Pioneer) 5 Soon Lee Street, #01-15 Pioneer Point Singapore 627607
Estimated Period of Repair:	0.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$12,000.00 (EST)
OMV :	\$-
PARF Rebate (1) :	\$-
Quota Premium Paid :	\$4,400.00 (EST)
COE Rebate (2) :	\$4,143.33
Total Rebate (1) + (2) = :	\$4,143.33

The total amount incurred will be Market Value \$12,000.00 minus Total Rebate \$4143.33 = \$7,856.67.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Mar 2022)	
Parts:	N/A	YAMAHA NMAX155 155cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ1580Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >