

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22000585/T1qy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 27/01/2022 SINGAPORE 068811 ATTN: KHOR SAW THENG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHC 1256L SLZ 2951M Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M03R2I Excess (\$) 0.00 14/01/2022 KHOR SAW THENG **Assign Date** Assign From **Vehicle Particulars & Condition** 2. TOYOTA SIENTA 1496 Make & Model C.C HIDDEN 2018 Engine No. Year of Reg. NHP1707114778 WHITE Chassis No. Colour Odometer 316599 KM Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 185/60 R15 WEST LAKE 6 mm WEST LAKE L/H Front Tyre 185/60 R15 6 mm 185/60 R15 WEST LAKE R/H Rear Tyre 6 mm WEST LAKE L/H Rear Tyre 185/60 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 13/01/2022 17/01/2022 ( 12:00 PM ) Inspect Date / Time Accident Date **GARAGE 13 PTE LTD** Survey held at 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000 5b. **Estimate Days of Repair** 

Report Ref No. CS3/ASM22000585/T1qy3e2

**Inspected By** 

MOHAMAD TAUFIKH

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

K.K.LAU CPT(RET)

6 Working Days

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.