

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944 (AfterSales)
Fax. 64796601 (Photocopy)
64796624



Steve (LKK)

26/1/22, 11.30 am

00-NM AL
EXCISE?

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 60617
Date Estimated : 14/01/2022
Prepared By : Chua Kee Sin

P/P, By Before 5 days

- ESTIMATE REPAIR FOR -
Chng Teng Ping Evan
29H Elias Terrace

Singapore 519853

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD9450Z	WBAEB12050B698044	19/03/2009	630i-C(A)	88785

DESCRIPTION

Replace front bumper include attachment etc and repair bonnet

Painting front bumper and bonnet

To check electrical wiring system at the front section
for proper function including adjustment of headlights.

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

To supply front emboss number plate.

Sundries.

VALUE

1275 / 2,125.00

2102 / 2,336.00

168 / 177.00

168 / 177.00

83.00

150.00

Total Labour 1: 5,048.00

DESCRIPTION

QTY

PRIC

VALUE

FRT BUMPER TOWING HINGE FLAP	1	54.30	54.30
FRT BUMPER LICENCE PLATE BASE PRIME	1	82.95	82.95
FRT BUMPER CARRIER COVER	1	38.10	38.10
FRT BUMPER (PDC)	1	1,993.70	1,993.70
FRT BUMPER CTR GRID	1	88.85	88.85
FRT BUMPER CARRIER	1	921.50	921.50
FRT BUMPER LH SHOCK ABSORBER	1	73.75	73.75
FRT BUMPER RH SHOCK ABSORBER	1	73.75	73.75
GRILLE LEFT (SCHWARZ)	1	191.85	191.85
GRILLE RIGHT (SCHWARZ)	1	191.85	191.85
EMBLEM GROMMET	2	0.95	1.90
BMW EMBLEM 82MM	1	72.85	72.85
PDC sensor	4	371.20	1,484.80

Total Parts : 5,270.15