

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 60617**
Date Estimated : **14/01/2022**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Chng Teng Ping Evan
29H Elias Terrace

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Singapore 519853

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD9450Z	WBAEB12050B6980	19/03/2009	630i-C(A)	88785

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
Replace front bumper include attachment etc and repair bonnet	1,275.00	0.00	1,275.00
Painting front bumper and bonnet	2,102.00	0.00	2,102.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	168.00	0.00	168.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To supply front emboss number plate.	83.00	0.00	83.00
Sundries.	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER RH MOUNT LATERAL	20.95	1.00	0.00	20.95
FRT BUMPER LICENCE PLATE BASE PRIME	82.95	1.00	0.00	82.95
FRT BUMPER (PDC)	1,993.70	1.00	0.00	1,993.70
FRT BUMPER CTR GRID	88.85	1.00	0.00	88.85
GRILLE LEFT (SCHWARZ)	191.85	1.00	0.00	191.85
GRILLE RIGHT (SCHWARZ)	191.85	1.00	0.00	191.85
EMBLEM GROMMET	0.95	2.00	0.00	1.90
BMW EMBLEM 82MM	72.85	1.00	0.00	72.85
RH DIRECTION INDICATOR LIGHT WHITE	524.60	1.00	0.00	524.60

SUPPLEMENTARY ITEMS

Total Labour :	3,946.00
Total Parts :	3,169.50
Total Labour & Parts :	7,115.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	7,115.50
GST @7%:	498.09
Grand Total :	7,613.59