



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2201333

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 11/03/2022
Reference CC6/CTI22000591/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMU 8898J
Insured Veh. GR 777P
Claim No. SNM22D200454/C02
Policy No. DMCVSNA00043022102
Accident Date 15/01/2022
Inspection Date 17/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI22000591/Upa3q2 Date: 11/03/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GR 777P	Veh. Inspected	SMU 8898J
	Policy No.	DMCVSNA00043022102	Coverage (\$)	0.00
	Claim No.	SNM22D200454/C02	Excess (\$)	0.00
	Assign From		Assign Date	17/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ A200 COMPT AMG	c.c	1332
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WDD1770872J046534	Colour	WHITE
	Odometer	33236 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	PIRELLI	7 mm
	L/H Front Tyre	225/45 R18	PIRELLI	7 mm
	R/H Rear Tyre	225/45 R18	PIRELLI	7 mm
	L/H Rear Tyre	225/45 R18	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/01/2022	Inspection Date	17/01/2022
	Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 8898J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR O/S DOOR	DENTED / WARPED	2,008.00	2,008.00
16	REAR O/S DOOR INNER TRIM BOARD CLIPS @\$10.00	NOT NECESSARY	160.00	-
1	REAR O/S FENDER	TO REPAIR SEE LABOUR	3,365.00	-
10	REAR O/S FENDER INNER GARNISH CLIPS @\$9.00	NOT NECESSARY	90.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,730.00	-
1	REAR BUMPER O/S SIDE RETAINER	NOT NECESSARY	125.00	-
10	REAR BUMPER CLIPS @\$9.00	NECESSARY	90.00	90.00
1	REAR O/S WHEEL TYRE	SERVICEABLE	680.00	-
	LESS 10% DISCOUNT		-	-209.80
			8,248.00	1,888.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR O/S SPORT RIM (SN)	WARPED	1,440.00	750.00
			1,440.00	750.00
	<u>LABOUR</u>			
	TO WIRING CHECK UP FOR REAR O/S DOOR WIRING SYSTEM.		60.00	20.00
	TO DIAGNOSE & RE-SET REAR O/S DOOR CENTRE LOCKING ,POWER WINDOW ,AIR-BAG SENSOR & FAULT CODE.		150.00	80.00
	TO CHECK & ADJUST WHEEL BALANCING & ALIGNMENT.		150.00	80.00
	TO REMOVE & REFIX REAR O/S DOOR INNER TRIM BOARD COVER ,REAR CUSHION SEAT ,CARPET ,FLOOR MAT ,REAR O/S FENDER GARNISH & NECESSARY PARTS ,TO ENALE REPAIR REAR O/S FENDER ,REAR O/S DOOR & NECESSARY PARTS.		300.00	80.00
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT REAR O/S DOOR ,REAR O/S FENDER & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR O/S FENDER AND REAR BUMPER .		1,200.00	600.00
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		1,350.00	600.00

Report Ref No. CC6/CTI22000591/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.		90.00	30.00
			3,300.00	1,490.00
GRAND TOTAL			12,988.00	4,128.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CC6/CTI22000591/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 8898J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 8898J

RE-INSPECTION

