

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3053/01/22 Your Ref: _____ Date: 17th JAN 2022

MS AMBER LIM WEI XIAN
BLK 108C, #11-29
Canberra Walk, S(753108)

Estimate cost of repair to MERCEDE BENZ A200 (A) 1.3 SUV - SMU 8898 J

1 pc rear o/s door	20/1000	\$ 2,008.00	
16 pcs rear o/s door inner trim board clips	11 @ \$ 10.00	160.00	X
1 pc rear o/s fender	R	3,365.00	X
10 pcs rear o/s fender inner garnish clips	11 @ \$ 9.00	90.00	X
1 pc rear bumper	R	1,730.00	
1 pc rear bumper o/s side retainer	11	125.00	X
10 pcs rear bumper clips	11 @ \$ 9.00	90.00	
1 pc rear o/s sport rim	wrap	1,440.00	750 s/n
1 pc rear o/s wheel tyre	su	680.00	X
		\$ 9,688.00	
	Less 10%	\$ 8,719.20	

To wiring check up for rear o/s door wiring system.	60.00	20
To diagnose & re-set rear o/s door centre locking, power window, air-bag sensor & fault code.	150.00	80
To check & adjust wheel balancing & alignment.	150.00	80
To remove & refix rear o/s door inner trim board cover, rear cushion seat, carpet, floor mat, rear o/s fender garnish & necessary parts, to enable repair rear o/s fender, rear o/s door & necessary parts.	300.00	80
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s door, rear o/s fender & necessary parts, to weld, renew & align above parts.	1,200.00	600
To putty & respray painting on all affected accident parts.	1,350.00	600
To respray Tuff-Kote on all affected accident parts.	90.00	30
	\$ 12,019.20	

Dollars :

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 2298
102
P-1888-20
S.N-750
L-1490
4118.2
-3702