



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (S) PTE LTD

INV No. AC2203642

1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV Date 13/06/2022
Reference CC4/QBE22000592/Dga3q2
Code QBE

PROFESSIONAL SERVICE FEE

Vehicle No. SJR 663Z
Insured Veh. EY 1111R
Claim No. VC014970
Policy No. 8-V0010891-MVA-R006
Accident Date 12/01/2022
Inspection Date 18/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (S) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC4/QBE22000592/Dga3q2	
			Date: 13/06/2022	
			Code: QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	EY 1111R	Veh. Inspected	SJR 663Z	
Policy No.	8-V0010891-MVA-R006	Coverage (\$)	0.00	
Claim No.	VC014970	Excess (\$)	0.00	
Assign From	JENNY	Assign Date	17/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN SHARAN	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WWWZZZ7NZCV021550	Colour	BLACK	
Odometer	103509 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R19	NEXEN	5 mm	
L/H Front Tyre	245/40 R19	NEXEN	5 mm	
R/H Rear Tyre	245/40 R19	NEXEN	5 mm	
L/H Rear Tyre	245/40 R19	NEXEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2022	Inspection Date	18/01/2022	
Survey held at	ALFRED AUTO SERVICES & SUPPLIES BLK 5035 ANG MO KIO 3 #01-355 ANG MO KIO INDUSTRIAL PARK 2 . SINGAPORE 569538			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 663Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT	NOT NECESSARY	4,390.00	-
1	SHARAN EMBLEM	NOT NECESSARY	98.00	-
1	2.0 TSI EMBLEM	NOT NECESSARY	90.00	-
1	REAR BUMPER	DISTORTED / DENTED	1,690.00	1,378.97
2	REAR BUMPER SIDE RETAINER @\$109.00	SERVICEABLE	218.00	-
1	REAR BUMPER CENTRE RETAINER BRACKET	BROKEN	230.00	230.00
1	REAR BUMPER SPONGE	NOT FITTED	192.00	-
1	REAR BUMPER REINFORCEMENT WITH HOOK	DENTED	1,990.00	865.80
1	REAR BUMPER LOWER SPOILER	DISTORTED	478.00	328.35
2	REAR BUMPER REFLECTOR @\$92.00	NOT NECESSARY	184.00	-
1	REAR EXHAUST	NOT NECESSARY	1,590.00	-
1	REAR EXHAUST HEAT SHIELD	SERVICEABLE	398.00	-
2	EXHAUST HANGER @\$58.00	NOT NECESSARY	116.00	-
1	EXHAUST BRACKET	NOT NECESSARY	86.00	-
1	REAR END PANEL	NOT NECESSARY	268.00	-
1	REAR END PANEL GARNISH INNER TRIM	NOT NECESSARY	499.00	-
1	REAR INNER END PANEL	NOT NECESSARY	298.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	298.00	-
1	SET REAR WINDSCREEN REPAIR KIT & SEALANT	NOT NECESSARY	180.00	-
1	REAR WINDSCREEN SEAL	NOT NECESSARY	60.00	-
4	PARKING SENSOR @\$298.00	2 PCS DAMAGED / 2 PCS NOT NECESSARY	1,192.00	596.00
4	PARKING SENSOR SEAL @\$38.00	2 PCS NECESSARY / 2 PCS NOT NECESSARY	152.00	9.00
4	PARKING SENSOR HOLDER @\$59.00	SERVICEABLE	236.00	-
1	PARKING SENSOR WIRE	NOT NECESSARY	399.00	-
1	TOWING HOOK COVER	CRACKED	189.00	189.00
	LESS 10% DISCOUNT		-	-359.71
			15,521.00	3,237.41

Report Ref No. CC4/QBE22000592/Dga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
4	REAR BUMPER SPOILER CLIPS @\$20.00 (SN)	NECESSARY	80.00	15.00
10	REAR BUMPER CLIPS @\$8.00(SN)	NECESSARY	80.00	20.00
			160.00	35.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT WIRING & CHECK.		180.00	30.00
	TO REPAIR & REFIT INTERIOR GARNISH ,SIDEBOARD & ALL ACCIDENT AFFECTED AREA.	NOT NECESSARY	280.00	-
	TO REMOVE & REFIT REAR WINDSCREEN .	NOT NECESSARY	180.00	-
	TO REMOVE & REFIT REAR EXHAUST MUFFLER.	NOT NECESSARY	280.00	-
	TO KNOCKING ,WELDING ,STRAIGHTENING & ALL ACCIDENT AFFECTED DAMAGED AREA.		1,000.00	600.00
	TO RESPRAY PAINTING ON ALL ACCIDENT INNER & OUTER ACCIDENT AFFECTED AREA.		900.00	300.00
	TO RUST PROOF ALL ACCIDENT AFFECTED AREA.	NOT NECESSARY	150.00	-
			2,970.00	930.00
GRAND TOTAL			18,651.00	4,202.41
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CC4/QBE22000592/Dga3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJR 663Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJR 663Z

RE-INSPECTION

