



# ALFRED AUTO

## Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538  
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391069/00 E  
Email: alfredauto@hotmail.com

Tyre &  
Sports Rim



Reference No.: 130122

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 13.01.2022

Cheah Geok Tseng (Xie Yuzhen)  
50 Cedar Avenue  
Singapore 349718.

Volkswagen Sharan 2.0 TSi

Estimate Repair Cost for Vehicle Reg. No: SJR 663 Z

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 Pc. Rear Boot	HH		4,390.00	X
1 Pc. Sharan Emblem	HH		98.00	X
1 Pc. 2.0 TSi Emblem	HH		90.00	X
1 Pc. Rear Bumper	Distance / Repair		1,690.00	✓ 1378.97
2 Pcs. Rear Bumper Side Retainer	SL	@ 109.00	218.00	X
1 Pc. Rear Bumper Centre Retainer Bracket	SL broken		230.00	✓
1 Pc. Rear Bumper Sponge	HF		192.00	X
1 Pc. Rear Bumper Reinforcement with Hook	Distance		1,990.00	✓ 865.80
1 Pc. Rear Bumper Lower Spoiler	Distance		478.00	✓ 328.35
4 Pcs. Rear Lower Spoiler Clips	HH	@ 20.00	80.00	✓ 151.34
2 Pcs. Rear Bumper Reflector	HH	@ 92.00	184.00	X
10 Pcs. Rear Bumper Clips	HH	@ 8.00	80.00	201- SH
1 Pc. Rear Exhaust	HH		1,590.00	X
1 Pc. Rear Exhaust Heat Shield	SL		398.00	X
2 Pcs. Exhaust Hanger	HH	@ 58.00	116.00	X
1 Pc. Exhaust Bracket	HH		86.00	X
1 Pc. Rear End Panel	HH		268.00	X
1 Pc. Rear End Panel Garnish Inner Trim	HH		499.00	X
1 Pc. Rear Inner End Panel	HH		298.00	X
1 Pc. Rear Windscreen Moulding	HH		298.00	X
1 Set. Rear Windscreen Repair Kit & Sealant	HH		180.00	X
1 Pc. Rear Windscreen Seal	HH		60.00	X
4 Pcs. Parking Sensor 2pc Dem 2pc HH	@ 298.00		1,192.00	✓ 596.00
4 Pcs. Parking Sensor Seal 2pc HH 2pc HH	@ 38.00/4.50		152.00	✓ 9.00
4 Pcs. Parking Sensor Holder	SL	@ 59.00	236.00	X
1 Pc. Parking Sensor Wire	HH		399.00	X
1 Pc. Towing Hook cover	Whole		189.00	✓
Total (Panels / Parts):			15,492.00	(SGD)

List 3597.12

SH 35.00

10% 3237.40





# ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538  
Tel: 6483 1586 Fax: 6483 4882 Reg. No. 391089/00 E  
Email: alfredauto@hotmail.com

Tyre &  
Sports Rim



## LABOR CHARGES

To remove & refit wiring & check.	180.00 30/-
To repair & refit interior garnish, sideboard & all Accident affected area.	280.00 HH
To remove & refit rear windscreen.	180.00 HH
To remove & refit rear exhaust muffler.	930.00 280.00 HH
To knocking, welding, straightening & all accident Affected damaged area.	1,000.00 600/-
To respray painting on all accident inner & outer accident affected area.	900.00 300/-
To rust proof all accident affected area.	150.00 HH

Total (Labor Charges): **2,970.00 (SGD)**

## TOTAL COST SUMMARY

PANELS / PARTS  
LABOR CHARGES

18/01/2022 10:00am

WAT Andrew

2/5mm 4 days.

15,492.00  
2,970.00

4202.40  
4/5 3,300/-

Grand Total: **18,462.00 (SGD)**

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or  
PAYNOW UEN 39108900E

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.