



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0045/2022/JT
DATE : 17-Jan-22
WIP : 63818

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY

YOUR INSURED VEH NO : SMB 165 T

MS First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

OWNER'S NAME : MR ABDUL JALIL BIN SYED IBRAHIM
ADDRESS : BLK 547 JURONG WEST STREET 42
#04-145
SINGAPORE 640547
TELEPHONE : HP +65 8182 9646
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10396621R00
VEHICLE NO : SKT 5764 K
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 16/6/2015
ENGINE NO : CZC 255415
CHASSIS NO : WAUZZZ8V9F1132725
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Jan-22
PLACE OF ACCIDENT : OPP JURONG GREEN CC



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKT 5764 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	S/N \$ (photo) 360.00	/
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM, TO REMOVE AND RENEW LHS WING MIRROR ASSY	S/N \$ 280.00	9 /
3	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	S/N \$ 350.00	/
4	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS. TO RENEW REAR CAMERA ASSY.	S/N \$ 280.00	X
5	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW LHS FRONT FENDER AND LHS REAR. TO REPAIR LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	700 \$ 2,400.00	2100
6	TO RESPRAY LHS FRONT FENDER, LHS WING MIRROR COVER, LHS REAR DOOR AND LHS SILL PANEL.	700 + 800 + 200 \$ 3,500.00	1700
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 7,362.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 5764 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - LH / <i>OD</i>	1	\$ 954.00 /	
2	FRONT FENDER ATTACHEMENT PARTS ? <i>X nn</i>	1	\$ 75.00	
3	FRONT FENDER BRACKET - LH ? <i>X nn</i>	1	\$ 46.00	
4	FRONT FENDER BRACE - LH ? <i>X nn</i>	1	\$ 107.00	
5	POP RIVET / <i>MC</i>	6	\$ 23.00 /	<i>22.8</i>
6	FRONT FENDER BRACKET - LH ? <i>X nn</i>	1	\$ 31.00	
7	FRONT FENDER CLOSING ELEMENT - LH <i>X nn</i>	1	\$ 37.00	
8	FRONT WHEEL HOUSING LINER - LH ? <i>X nn</i>	1	\$ 183.00	
9	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS ? <i>X nn</i>	1	\$ 93.00	
10	WING MIRROR MOUNTING - LH ? <i>X nn</i>	1	\$ 1,130.00	
11	WING MIRROR CAP - LH <i>X R</i>	1	\$ 180.00	
12	WING MIRROR GLASS <i>X</i>	1	\$ 239.00	
13	REAR DOOR - LH / <i>OD</i>	1	\$ 3,265.00 /	
14	REAR DOOR BUNGS - LH / <i>MC</i>	1	\$ 5.00 /	<i>4.5</i>
15	REAR DOOR OUTER SEAL - LH / <i>MC</i>	1	\$ 179.00 /	<i>178.5</i>
16	BONDING AGENT <i>X MC X nn</i>	1	\$ 51.00	
17	CLEANING SOLUTION <i>X MC X nn</i>	1	\$ 74.00	
18	APPLICATOR <i>X nn</i>	1	\$ 8.00	
19	REAR DOOR ATTACHEMENT PARTS <i>X nn</i>	1	\$ 134.00	
20	REAR DOOR CATCH - LH ? <i>X nn</i>	1	\$ 94.00	
21	REAR LID LOCK ACTUATOR <i>X nn</i>	1	\$ 1,478.00	
22	STONE CHIP <i>X nn</i>	S/N	\$ 180.00	
23	SUNDRIES ? <i>MC</i>		\$ 350.00	<i>5-40</i>
TOTAL SPARE PARTS		:	\$ 8,916.00	
TOTAL LABOUR CHARGES		:	\$ 7,362.00	
GRAND TOTAL		:	\$ 16,278.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

4/2/21, 2.11pm

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve CLKK)
OD- M PL
EXCESS - ?
P/P
by RL by, 5 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: