



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD  
C/O SEAH ONG & PARTNERS LLP  
36 ROBINSON ROAD #12-03 CITY HOUSE  
SINGAPORE 068877

Ref: CC4/ASM22000598/Kpa3q2

Date: 10/03/2023

Code: HSB

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 7116M	Veh. Inspected	SMA 6341S
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	22.30318	Excess (\$)	0.00
Assign From	HENG XINYI (SEAH ONG)	Assign Date	17/01/2022

### 2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71207495	Colour	METALLIC BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	9 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	9 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

Accident Date	13/01/2022	Inspection Date	17/01/2022
Survey held at	CAR TIMES AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29/30 BARTLEY BIZ CENTRE SINGAPORE 417807		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------