

ASS. REC. BY:

REF:

ASM/ 220003981ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: \$74k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA 63415 Yr Regn: 06, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Honda Shuttle C.C. 1496Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C.No: GP7 - 12074P5Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 13/1/22 D.O.I. 17/1/2022Survey held at 1.25pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Bottom \$1012 11 Sup & 21.800 Cash

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Notarized
L1 By \$ 21,800/-
Penny the Pain
18 days

MODEL: HONDA SHUTTLE

DESCRIPTION	REPAIRER'S ESTIMATE(\$\$)
PARTS (LIST ITEMS)	
FRONT BUMPER 1050	By Hn \$ 1,210.00
FRONT BUMPER RETAINER LHS	CM \$ 30.00
FRONT BUMPER RETAINER RHS	CM \$ 30.00
FRONT FOG LAMP LHS	Mis \$ 310.00
FRONT FOG LAMP RHS	Sn \$ 310.00
FRONT FOG LAMP COVER LHS 33.20	Mis \$ 70.00
FRONT FOG LAMP COVER RHS	Sn \$ 70.00
FRONT BUMPER LOWER COVER 181	CM \$ 200.00
FRONT BUMPER LOWER GRILLE	CM \$ 120.00
FRONT GRILLE 395	CM \$ 410.00
FRONT GRILLE OUTER GARNISH (CHROME)	CM \$ 300.00
FRONT GRILLE LOWER GARNISH (CHROME)	CM \$ 230.00
FRONT GRILLE CENTRE BRACKET	\$ Bz 90.00
FRONT EMBLEM	Sn \$ 40.00
HEADLAMP LHS 2227.00	CM \$ 2,320.00
HEADLAMP RHS 4	my Dis \$ 2,320.00
HEADLAMP BRACKET LHS	\$ CM 60.00
HEADLAMP BRACKET RHS	\$ Sn 60.00
FRONT REINFORCEMENT	Bz \$ 330.00
SUPPORT PANEL	Bz \$ 680.00
FRONT WHEELHOUSE LHS	Bz \$ 510.00
FRONT WHEELHOUSE RHS	n \$ 510.00
FRONT WHEELHOUSE EXTENSION LHS	\$ Bz 200.00
FRONT WHEELHOUSE EXTENDER RHS	\$ n 200.00
FRONT FENDER LHS	Bz \$ 460.00
FRONT FENDER RHS	Bz \$ 460.00
FRONT FENDER INNER SHIELD LHS	Tn \$ 120.00
FRONT FENDER INNER SHIELD RHS	CM \$ 120.00
FRONT BONNET	Bz \$ 720.00
FRONT BONNET HINGE LHS	\$ Bz 50.00
FRONT BONNET HINGE RHS	\$ Bz 50.00
FRONT BONNET LOCK ASSY	\$ Bz 200.00

145

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 2,500.00	1200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 2,500.00	1400
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	30
4	To provide anti-rust treatment on affected areas	\$ 100.00	✓
5	Remove & refit front sensor	\$ 100.00	X
6	Dignostic Check	\$ 100.00	✓
7	Remove & refit engine	\$ 400.00	250
8	Remove & refit dashboard	\$ 300.00	250
	Labour Total :	\$ 6,100.00	
	TOTAL (PARTS & LABOUR):	\$ 35,649.00	

VEHICLE NO: SMA6341S
CHASSIS NO: GP7-1207495

MODEL: HONDA SHUTTLE

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>		
AIR FILTER BOX ASSY 325		MJ CM \$ 430.00
FUSE BOX ASSY		MJ CM \$ 860.00
FUSE BOX CONTROL UNIT 1250		DCA \$ 1,560.00
BATTERY LOWER HOLDER		CM \$ 100.00
BATTERY TOP COVER (RED)		CN \$ 50.00
		\$ 3,000.00
	20%	\$ 600.00
		\$ 2,400.00
<u>SPECIAL NETT ITEMS</u>		
TOTAL:		\$ -
	TOTAL PARTS	\$ 2,400.00

<u>LABOUR</u>		
	TOTAL:	\$ -
(LABOUR + PARTS) TOTAL:		\$ 2,400.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	805A
Vehicle Details	
Vehicle No.:	SMA6341S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Jan 2022
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	LEB6549220
Chassis No.:	GP71207495
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$22,364.00
Original Registration Date:	14 Jun 2018
First Registration Date:	14 Jun 2018
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jun 2028
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,700.00
COE Rebate Amount:	\$24,339.00
Total Rebate Amount:	\$28,089.00

The information contained herein is correct as at 17 Jan 2022

OK