



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI22000602/Aqf3n2

Date: 19/05/2022

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 5127E	Veh. Inspected	SKX 6186B
Policy No.		Coverage (\$)	0.00
Claim No.	C10013443/CD	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	17/01/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZSU600062934	Colour	WHITE
Odometer	81713 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R18	MICHELIN	6 mm
L/H Front Tyre	235/55 R18	MICHELIN	6 mm
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/01/2022	Inspection Date	18/01/2022
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**