

Shiau Chan (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Wednesday, 23 February 2022 11:25 AM
To: Shiau Chan (LKKAuto)
Subject: RE: FCI-TP SLS 7295C SURVEYED BY KENNETH (OUR REF: CS/FCI22000604/Kqf3)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SLS7295C, FOUND NO WHEEL ALIGNMENT REPORT FOR UNDERCARRIAGE PARTS REPLACED.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 23 February, 2022 10:46 AM
To: Simon Ho (LKKAuto)
Subject: FCI-TP SLS 7295C SURVEYED BY KENNETH (OUR REF: CS/FCI22000604/Kqf3)

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)