



Address: 60 Jalan Lam Huat, #03-72
CARROS CENTER, Singapore 737869

Repair Estimate

Date: 08 Jan 2022

Vehicle: SJM4269D
Make/Model: Toyota Camry
Chassis No. : MR053BK4107036751

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	Bonnet / Bue	1	\$ 670.20	\$ 670.20
2	Bonnet RH hinge X	1	\$ 64.80	\$ 64.80
3	Bonnet LH hinge X	1	\$ 64.80	\$ 64.80
4	Bonnet lock X	1	\$ 166.10	\$ 166.10
5	Bonnet insulator X	1	\$ 231.60	\$ 231.60
6	Front bumper / Bue	1	\$ 624.70	\$ 624.70
7	Front bumper RH side retainer X	1	\$ 59.89	\$ 59.89
8	Front bumper RH chrome moulding X	1	\$ 193.70	\$ 193.70
9	Front bumper LH chrome moulding X	1	\$ 193.70	\$ 193.70
10	Front bumper RH fog lamp X	1	\$ 384.50	\$ 384.50
11	RH headlamp assy / CRA	1	\$ 1,001.40	\$ 1,001.40
12	RH front fender / Bue	1	\$ 856.30	\$ 856.30
13	RH front fender emblem / Bue	1	\$ 56.80	\$ 56.80
14	RH front fender splash shield / Bue	1	\$ 184.50	\$ 184.50
15	RH front fender encloser X	1	\$ 68.70	\$ 68.70
16	RH front fender inner panel X	1	\$ 703.70	\$ 703.70
17	RH front sport rim (original) / C.A.T.	1	\$ 934.50	\$ 934.50
18	RH front sport rim centre emblem cover X	1	\$ 76.30	\$ 76.30
19	RH front lower arm	1	\$ 605.30	\$ 605.30
20	RH front lower arm ball joint X	1	\$ 235.60	\$ 245.60
21	RH front shock absorber top mounting X	1	\$ 161.00	\$ 161.00
22	RH front shock absorber top mounting bearing X	1	\$ 32.00	\$ 32.00
23	RH front shock absorber X	1	\$ 598.60	\$ 598.60
24	RH front knuckle arm	1	\$ 634.20	\$ 634.20
25	RH front wheel bearing with hub	1	\$ 265.30	\$ 265.30
26	RH front tie rod X	1	\$ 151.20	\$ 151.20
27	RH front tie rod end X	1	\$ 76.40	\$ 76.40

28	RH front drive shaft X	1	\$ 1,008.00	\$ 1,008.00
29	RH front ABS sensor X	1	\$ 211.20	\$ 211.20
30	Steering rack and pinion X	1	\$ 2,664.00	\$ 2,664.00
31	Front undercarriage crossmember X	1	\$ 1,161.10	\$ 1,161.10
32	RH front door X Repri	1	\$ 1,304.20	\$ 1,304.20
33	RH front door protector	1	\$ 137.60	\$ 137.60
34	RH front door protector chrome moulding	1	\$ 78.30	\$ 78.30
35	RH front door weatherstrip X	1	\$ 167.80	\$ 167.80
36	Front windscreen glass rubber moulding X	1	\$ 113.00	\$ 113.00
37	Front windscreen glass wiper garnish RH cover X	1	\$ 32.90	\$ 32.90
38	Front windscreen glass wiper garnish X	1	\$ 303.20	\$ 303.20
			Total	\$ 16,487.09
			Less 25%	\$ 4,121.77
			Total	\$ 12,365.32

S/Nett Items				
1	Bonnet insulator clips	1set	\$ 70.00	\$ 70.00
2	Front bumper clips	1set	\$ 70.00	\$ 70.00
3	RH front fender splash shield clips	1set	\$ 60.00	\$ 60.00
4	RH front fender inner panel joint sealant X	1	\$ 75.00	\$ 75.00
5	Brake fluid X	1	\$ 60.00	\$ 60.00
6	RH front door inner trim board clips X	1set	\$ 60.00	\$ 60.00
7	RH front tyre	1	\$ 400.00	\$ 400.00
8	Front windscreen glass sealant X	1	\$ 70.00	\$ 70.00
9	Front windscreen glass inner seal X	1	\$ 50.00	\$ 50.00
			Total	\$ 915.00

LABOUR				
1	Panel beating on affected areas	1	\$ 1,600.00	\$ 1,600.00
2	Spray paint on affected areas	1	\$ 1,300.00	\$ 1,300.00
3	To check wiring and lighting system	1	\$ 100.00	\$ 100.00
4	To refocus and adjust headlamps assy	1	\$ 60.00	\$ 60.00
5	To apply rust proofing on affected areas	1	\$ 100.00	\$ 100.00
6	To remove and replace front undercarriage parts	1	\$ 550.00	\$ 550.00
7	To remove, replace and balance RH front sport rim with	1	\$ 70.00	\$ 70.00
8	tyre			
9	To test drive and adjust wheel alignment system	1	\$ 120.00	\$ 120.00
10	To remove and refit RH front door inner components to		\$ 120.00	\$ 120.00
11	new door			
12	To remove and refit front windscreen glass	1	\$ 220.00	\$ 220.00

500.
800
30
60.
200.
60.
X
X

Total Labour	\$ 4,240.00
Parts Replacement Amount	\$ 13,280.32
Total Amount	\$ 17,520.32

6 Days.

L/S.

After repair photos.

Gina Qian - 82880282

18/1/22.