

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 5481B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	TO REPAIR SEE LABOUR	1,380.00	-
1	FRONT GRILLE	CUT	590.00	590.00
1	FRONT GRILLE LOGO	CUT	180.00	146.00
1	O/S HEADLAMP	NOT NECESSARY	820.00	-
1	FRONT BUMPER	DEFORMED	1,160.00	1,160.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	910.00	-
1	FRONT BUMPER TOW COVER	DEFORMED	72.00	72.00
1	FRONT BUMPER COVER	CUT	480.00	480.00
15	FRONT BUMPER CLIPS @\$22.00	NECESSARY	330.00	30.00
1	FRONT NUMBER PLATE HOLDER	MISSING	220.00	160.00
1	FRONT BUMPER LOWER AIR GRILLE	NOT NECESSARY	710.80	-
2	FRONT BUMPER SIDE HOLDER @\$110.35	NOT NECESSARY	220.70	-
2	FRONT BUMPER BRACKET @\$140.00	NOT NECESSARY	280.00	-
1	FRONT BUMPER FOAM	CRACKED	214.00	214.00
	LESS 10% DISCOUNT		-756.75	-
	LESS 50% DISCOUNT		-	-1,426.00
			6,810.75	1,426.00
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	DAMAGED	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING FRONT PORTION OF THE AFFECTED PORTION.		700.00	400.00
	PANEL BEATING,KNOCKING AND STRAIGHTEN FRONT PORTION AND THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BONNET.		800.00	300.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		80.00	30.00
			1,580.00	730.00
	GRAND TOTAL		8,440.75	2,206.00

Report Ref No. CS/INC22000613/Avf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,200.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. CS/INC22000613/Avf3e2



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.