



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN: CHESTER CHONG

Ref: CS/INC22000613/Avf3e2

Date: 05/04/2022

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                        |                |            |
|--------------|------------------------|----------------|------------|
| Insured Veh. | SNB 7518B              | Veh. Inspected | GBG 5481B  |
| Policy No.   |                        | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1158582-001         | Excess (\$)    | 0.00       |
| Assign From  | HAZALYSA BINTE IBRAHIM | Assign Date    | 18/01/2022 |

### 2. Vehicle Particulars & Condition

|              |                   |              |          |
|--------------|-------------------|--------------|----------|
| Make & Model | FIAT DOBLO        | c.c          | 1598     |
| Engine No.   | HIDDEN            | Year of Reg. | 2017     |
| Chassis No.  | ZFA26300006H17671 | Colour       | GREY     |
| Odometer     | 90826 KM          | Steering     | IN ORDER |
| Brakes       | IN ORDER          | Modification | NIL      |
| General      | GOOD              |              |          |

### 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 205/60 R16 | KAPSEN | 6 mm    |
| L/H Front Tyre | 205/60 R16 | KAPSEN | 6 mm    |
| R/H Rear Tyre  | 205/60 R16 | KAPSEN | 6 mm    |
| L/H Rear Tyre  | 205/60 R16 | KAPSEN | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

|                |   |                     |                         |
|----------------|---|---------------------|-------------------------|
| Accident Date  | 11/01/2022  | Inspect Date / Time | 18/01/2022 ( 10:55 AM ) |
| Survey held at | SUCCESS UNITED PTE LTD<br>2 KAKI BUKIT AVE 2<br>#01-33 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                     |                         |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days