



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000614/Kty3n2	
			Date: 26/05/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBK 7824L	Veh. Inspected	SLD 1922U
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200107/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	18/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA CAMRY (A)	c.c	2487
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JTNB23HK603060238	Colour	METALLIC SILVER
	Odometer	30981 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	245/35 R19	YOKOHAMA	8 mm
	L/H Front Tyre	245/35 R19	YOKOHAMA	8 mm
	R/H Rear Tyre	245/35 R19	YOKOHAMA	8 mm
	L/H Rear Tyre	245/35 R19	YOKOHAMA	8 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	07/01/2022	Inspection Date	20/04/2022
	Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	