



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000622/Uvf3e2	
			Date: 17/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 4737X	Veh. Inspected	SKS 6259B	
Policy No.	D20MTHCVE001400	Coverage (\$)	0.00	
Claim No.	CMTD2200193/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	18/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JM6CW1071F0121341	Colour	RED	
Odometer	111526 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	KAPSEN	6 mm	
L/H Front Tyre	205/55 R16	KAPSEN	6 mm	
R/H Rear Tyre	205/55 R16	KAPSEN	6 mm	
L/H Rear Tyre	205/55 R16	KAPSEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION, O/S AND N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2022	Inspection Date	18/01/2022	
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	