

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI22000629/TVCN2**Date:** 11/02/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR000568
Claimant Vehicle No :	SHA2258K	Insured Vehicle No :	SMS378G
Date of Loss:	14/01/2022	Nature of Claim:	TP
		Claim No:	M2200334

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2258K		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR2G76594
Reg. Date:	15/04/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU303091262
Colour:	Blue	Odometer:	188947 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,551.52	5,551.52	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,770.00	1,410.00	360.00	20.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,332.52	6,972.52	360.00	4.91
Approved Total (Overridden) (S\$)		6,972.50		
(S\$)	7,332.52	6,972.50	360.02	4.91
+ GST 7.00/7.00% (S\$)	513.28	488.08	25.20	4.91
Nett Amount (S\$)	7,845.80	7,460.58	385.22	4.91

INSPECTION

Date of Assignment:	18/01/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	14/01/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 2 cents -Finalise confirm amount: \$6,972.50

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Feb 2022)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2258K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	-	*458.60 FL
2	1		*REAR BUMPER CTR MOULDING	Deformed	552.60 FL	-	*552.60 FL
3	1		*REAR BUMPER TOW COVER	Missing	82.70 FL	-	*82.70 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	-	*318.80 FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
6	1		*REVERSE SENSORS	Not Working	135.70 F	-	*135.70 FS
Supplementary #1							
7	1		*BOOTLID	Bent	1,126.60 FL	-	*1,126.60 FL
8	1		*BOOTLID GARNISH	Cracked	889.70 FL	-	*889.70 FL
9	1		*REAR WINDSCREEN GLASS (UPPER)	Necessary	1,778.30 FL	-	*1,778.30 FL
10	1		*REAR LOWER GLASS-BLACK	Necessary	1,569.70 FL	-	*1,569.70 FL
11	1		*BOOTLID (HYBRID)	Necessary	52.40 FL	-	*52.40 FL
12	1		*BOOTLID (PRIUS)	Necessary	60.80 FL	-	*60.80 FL
13	1		*BOOTLID (TOYOTA STAR)	Necessary	52.90 FL	-	*52.90 FL
14	1		*BOOTLID COMFORTDELGRO	Necessary	30.00 F	-	*30.00 FS
15	1		*BOOTLID 65521111	Necessary	30.00 F	-	*30.00 FS
16	1		*BOOTLID APPS	Necessary	40.00 F	-	*40.00 FS
17	2		*WINDSCREEN SEALANT	Necessary	92.00 F	-	*92.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,292.80	7,292.80
- List Item Discount on L Items 25.00/25.00% (\$)	1,741.28	1,741.28
Total Parts (\$)	5,551.52	5,551.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	30.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
4	PANEL BEATING - ADDITIONAL BOOTLID	New	400.00	350.00
5	SPRAY PAINTING - BOOTLID	New	300.00	250.00
6	R/I BOOTLID GLASSES	New	250.00	180.00
Gross Labour Cost (\$\$)			1,770.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >