

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT LONPAC INSURANCE BHD CS3/LPC22000632/Vtf3e2 Ref: 300 BEACH ROAD #17-04/07 THE CONCOURSE Date: 25/01/2022 SINGAPORE 199555 Code: LPC2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SLK 2343Y** SJS 1959J Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. 21/22/22/VP05/025382 Excess (\$) 0.00 18/01/2022 **GERALD POH Assign Date** Assign From 2. **Vehicle Particulars & Condition** TOYOTA PRIUS HYBRID 1798 Make & Model C.C HIDDEN 2017 Engine No. Year of Reg. JTDKB3FU403544059 WHITE Chassis No. Colour 169560 KM Odometer Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/65 R15 KUMHO 6 mm 195/65 R15 **KUMHO** L/H Front Tyre 6 mm 195/65 R15 **KUMHO** R/H Rear Tyre 6 mm **KUMHO** L/H Rear Tyre 195/65 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 13/01/2022 18/01/2022 (02:00 PM) Inspect Date / Time Accident Date A-TEC AUTOMOTIVE PTE LTD Survey held at 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875 5a. Remarks

Report Ref No. CS3/LPC22000632/Vtf3e2

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser