



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name / Sim Kat Tee Reg No/Reg Date SCA7876C / 28/02/201 Date In/Mileage / 55724 Chassis No KNAFJ411MJ5764840 Engine No G4FGJH695303 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	18/01/2022/ 10:07	BLE	261 / Edwin Caina	45736

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 1 R 2 3 X 400 RENEW FR BUMPER, BONNET & FR SUPPORT REPAIR RHF FENDER				1200 2000.00
E PNT98000 1 RESPRAY FR BUMPER, BONNET & RHF FENDER 2 X 350				700 1050.00
E PNT88000 REMOVE & REFIT AC COND & RADIATOR (photo)				100.00
M SUNDRY TOP UP AC GAS				80.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY SUPPLY FR NUMBER PLATE WITH CASING cut				50.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00
M SUNDRY SUPPLY BODY PNL SEALANT				40.00
M SUNDRY MK Sundries				20.00
M LAMP ASSY-HEAD, RH BR	1.00	810.00	20.00	648.00
M PANEL ASSY-HOOD X R	1.00	1384.00	20.00	1107.20
M CARRIER ASSY-FRONT, END MODULE BR (photo)	1.00	675.00	20.00	540.00
M LATCH ASSY-HOOD X NN	1.00	65.00	20.00	52.00
M ORNAMENT-KIA NO.115 MK	1.00	32.00	20.00	25.60
M STRIP ASSY-FR BUMPER UPR BR	1.00	29.00	20.00	23.20
M GARNISH-RADIATOR GRILLE, UPR BR	1.00	54.00	20.00	43.20
M GRILLE ASSY-RADIATOR BR	1.00	160.00	20.00	128.00
M COVER-FR BUMPER DO	1.00	633.00	20.00	506.40
M CAP-FRONT HOOK BR	1.00	9.00	20.00	7.20
M MOULDING-FRT BPR LICENSE PLATE BR	1.00	18.00	20.00	14.40
M LIP ASSY-FRONT BUMPER X NN	1.00	55.00	20.00	44.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name / Sim Kat Tee Reg No/Reg Date SCA7B76C / 28/02/201 Date In/Mileage / 55724 Chassis No KNAFJ411MJ5764840 Engine No G4FGJH695303 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	18/01/2022/ 10:07	BLE	261 / Edwin Caina	45736			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
					1.00	91.00	20.00	72.80
M	MOULDING-FRONT BUMPER A/INTAKE				1.00	33.00	20.00	26.40
M	AIR DUCT-FR BUMPER, RH				1.00	6.00	20.00	4.80
M	DUCT ASSY-AIR CURTAIN, RH				1.00	84.00	20.00	67.20
M	ABSORBER-FRONT BUMPER ENERGY				1.00	114.00	20.00	91.20
M	STIFFNER-FR BPR LWR				1.00	496.00	20.00	396.80
M	RAIL ASSY-FR BUMPER				1.00	13.00	20.00	10.40
M	BRACKET-FR BUMPER SIDE MTG, RH				1.00	19.00	20.00	15.20
M	GUARD-AIR, LH				1.00	19.00	20.00	15.20
M	GUARD-AIR, RH				1.00	681.00	20.00	544.80
M	CONDENSER ASSY-COOLER				1.00	546.00	20.00	436.80
M	RADIATOR ASSY				1.00	623.00	20.00	498.40
M	BLOWER ASSY				1.00	26.00	23.00	20.02
M	COOLANT (4L)							

SURVEYOR NAME: Sten CLKKSURVEYOR SIGNATURE: DD-NA ALDATE: EXPERI - 1REMARKS: P/PMy P/L by 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and approved by LKK Auto Consultants approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

	Nett	8,869.22
7% GST on	8869.22	620.85
Total Payable		9,490.07

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.