



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Sim Kat Tee Reg No/Reg Date SCA7876C / 28/02/201 Date In/Mileage / 55724 Chassis No KNAFJ411MJ5764840 Engine No G4FGJH695303 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	18/01/2022/ 10:07	BLE	261 / Edwin Caina	45736			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E PNT88000	1	R	2				2000.00	
RENEW FR BUMPER , BONNET & FR SUPPORT				3 X	400		1200	
REPAIR RHF FENDER								
E PNT98000	1						1050.00	
RESPRAY FR BUMPER , BONNET & RHF FENDER				2 X	350		700	
E PNT88000							100.00	
REMOVE & REFIT AC COND & RADIATOR				(photo)				
M SUNDRY							80.00	
TOP UP AC GAS								
A 54900099							30.00	
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901							120.00	
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY							50.00	
SUPPLY FR NUMBER PLATE WITH CASING				CUT				
M SUNDRY							40.00	
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY							40.00	
SUPPLY BODY PNL SEALANT								
M SUNDRY							20.00	
Sundries								
M LAMP ASSY-HEAD,RH			BR		1.00	810.00	20.00	648.00
M PANEL ASSY-HOOD			X R		1.00	1384.00	20.00	1107.20
M CARRIER ASSY-FRONT END MODULE			BR	(photo)	1.00	675.00	20.00	540.00
M LATCH ASSY-HOOD					1.00	65.00	20.00	52.00
M ORNAMENT-KIA NO.115			MC		1.00	32.00	20.00	25.60
M STRIP ASSY-FR BUMPER UPR					1.00	29.00	20.00	23.20
M GARNISH-RADIATOR GRILLE,UPR			BR		1.00	54.00	20.00	43.20
M GRILLE ASSY-RADIATOR			BR		1.00	160.00	20.00	128.00
M COVER-FR BUMPER			00		1.00	633.00	20.00	506.40
M CAP-FRONT HOOK					1.00	9.00	20.00	7.20
M MOULDING-FRT BPR LICENSE PLATE			BR		1.00	18.00	20.00	14.40
M LIP ASSY-FRONT BUMPER					1.00	55.00	20.00	44.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Sim Kat Tee Reg No/Reg Date SCA7876C / 28/02/201 Date In/Mileage / 55724 Chassis No KNAFJ411MJ5764840 Engine No G4FGJH695303 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	18/01/2022/ 10:07	BLE	261 / Edwin Caina	45736
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M MOULDING-FRONT BUMPER A/INTAKE		1.00	91.00	20.00	72.80
M AIR DUCT-FR BUMPER,RH		1.00	33.00	20.00	26.40
M DUCT ASSY-AIR CURTAIN,RH		1.00	6.00	20.00	4.80
M ABSORBER-FRONT BUMPER ENERGY	BR	1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR		1.00	114.00	20.00	91.20
M RAIL ASSY-FR BUMPER	ON	1.00	496.00	20.00	396.80
M BRACKET-FR BUMPER SIDE MTG,RH	BR	1.00	13.00	20.00	10.40
M GUARD-AIR,LH		1.00	19.00	20.00	15.20
M GUARD-AIR,RH	CR4	1.00	19.00	20.00	15.20
M CONDENSER ASSY-COOLER		1.00	681.00	20.00	544.80
M RADIATOR ASSY		1.00	546.00	20.00	436.80
M BLOWER ASSY		1.00	623.00	20.00	498.40
M COOLANT (4L)		1.00	26.00	23.00	20.02

Estimate

SURVEYOR NAME: Sten CLKK
 SURVEYOR SIGNATURE: DD-NM AL
 DATE: EXRRI - ?
 REMARKS: P/P
My B/L
7 dy

Confirm & accepted by

	Nett	8,869.22
7% GST on	8869.22	620.85
Total Payable		9,490.07

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.