



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name / DESMOND TAN JUN YUAN Reg No/Reg Date SMJ4963M*KC17/ 08/03/201 Date In/Mileage / 0 Chassis No KNAF3416MK5031070 Engine No G4FGJH722036 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	18/01/2022/ 12:56	BLE	261 / Edwin Caina	45746		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							3200.00
RENEW FR BUMPER, FR SUPPORT, BONNET, LHF FENDER & RHF FENDER 5 x 499							2900
REPAIR LHF DOOR, RHF DOOR & FR A PILLAR LH/RH							3840.00
E PNT98000							2400
RESPRAY FR BUMPER, BONNET, LHF FENDER, RHF FENDER, 480 (CR5) x 5							
LHF DOOR, RHF DOOR & FR A PILLAR LH/RH							100.00
E PNT88000							80.00
REMOVE & REFIT AC COND & RADIATOR							30.00
M SUNDRY							120.00
TOP UP AC GAS							50.00
A 54900099							120.00
CHECK WIRING ELECTRICAL SYSTEM							50.00
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							80.00
M SUNDRY							40
SUPPLY FR NUMBER PLATE WITH CASING BR							40
M SUNDRY							20.00
APPLY ANTI CORROSION ON AFFECTED AREAS							506.40
M SUNDRY							388.00
SUPPLY BODY PNL SEALANT							262.40
M SUNDRY							30.40
Sundries				1.00	633.00	20.00	172.80
M COVER-FR BUMPER BR				1.00	485.00	20.00	172.80
M GRILLE-FRONT BUMPER BR				1.00	328.00	20.00	114.40
M GRILLE ASSY-RADIATOR BR				1.00	38.00	20.00	114.40
M GARNISH-RADIATOR GRILLE BR				1.00	216.00	20.00	67.20
M MOULDING-FRONT BUMPER, LH CUT				1.00	216.00	20.00	91.20
M MOULDING-FRONT BUMPER, RH CUT				1.00	143.00	20.00	17.60
M LAMP ASSY-SIDE REPEATER, LH 7 x mm				1.00	143.00	20.00	
M LAMP ASSY-SIDE REPEATER, RH 7 x mm				1.00	84.00	20.00	
M ABSORBER-FRONT BUMPER ENERGY BR				1.00	114.00	20.00	
M STIFFNER-FR BPR LWR 7 x mm				1.00	22.00	20.00	
M BRACKET-FR BUMPER UPR SIDE MTG 7 x mm				1.00			

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name / DESMOND TAN JUN YUAN Reg No/Reg Date SMJ4963M*KC17/ 08/03/201 Date In/Mileage / 0 Chassis No KNAF3416MK5031070 Engine No G4FGJH722036 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	18/01/2022/ 12:56	BLE	261 / Edwin Caina	45746
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET-FR BUMPER UPR SIDE MTG	X m	1.00	22.00	20.00	17.60
M WIRING ASSY-BUMPER EXTENSION	BR	1.00	207.00	20.00	165.60
M ULTRASONIC SENSOR ASSY-P.A.S	X m	4.00	163.00	20.00	521.60
M ORNAMENT-KIA NO.115	MC	1.00	32.00	20.00	25.60
M BEAM COMPLETE-FR BUMPER	DD	1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE	BR	1.00	675.00	20.00	540.00
M PANEL ASSY-HOOD	DD	1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD,LH	BT	1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD,RH	BT	1.00	43.00	20.00	34.40
M PANEL-FENDER,LH	DD	1.00	430.00	20.00	344.00
M PANEL-FENDER,RH	DD	1.00	430.00	20.00	344.00
M PAD-HOOD INSULATING	MC	1.00	156.00	20.00	124.80
M CLIP-HOOD INSULATING PAD MTG	DD	13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD	BT	1.00	103.00	20.00	82.40
M LAMP ASSY-HEAD,LH	BR	1.00	2210.00	20.00	1768.00
M LAMP ASSY-HEAD,RH	BR	1.00	2210.00	20.00	1768.00
M GUARD-AIR,LH	BR	1.00	28.00	20.00	22.40
M GUARD-AIR,RH	BR	1.00	28.00	20.00	22.40
M CONDENSER ASSY-COOLER	DD	1.00	687.00	20.00	549.60
M RADIATOR ASSY	X m	1.00	646.00	20.00	516.80
M BLOWER ASSY	X m	1.00	656.00	20.00	524.80
M GUARD ASSY-FRONT WHEEL,LH	X m	1.00	95.00	20.00	76.00
M GUARD ASSY-FRONT WHEEL,RH	X m	1.00	95.00	20.00	76.00

SURVEYOR NAME :

Steve (LKK) 18/1/22, 3:30pm

SURVEYOR SIGNATURE :

DD-MAL

DATE :

EX-11-?

REMARKS :

P/P, My BL Y

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

87 djs

	Nett	18,745.60
7% GST on	18745.60	1312.19
Total Payable		20,057.79

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.