

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000037 / ICCUA2	M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925	
		Document No. 0		
		Document Date 18/01/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZVW40R	AWXEBW Q3	23/02/2021	SMY1960L	0	12811	75/DS/SMY1960L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU10J059924	2ZR2F74130	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:GBG3995Z ACC DATE:17/01/2022 TOW IN:17/01/2022 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 / 100.00
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST				180.00 162
3	S	BP-SUBLET RESET ECU UPON COMPLETION OF REPAIR				180.00 162
4	B	BP-LAB2 DRILL HOLE & INSTALL REVERSE SENSOR				180.00 162
5	B	BP-LAB2 TRANSFER TAILGATE MACH				720.00 648
6	B	BP-LAB2 REPL ACC AFF AREA 770 x 4 STRAIGHTEN & PANEL BEAT ACC AFF AREA				2880 5040.00 2592
7	B	BP-RES2 RESPRAY ACC AFF AREA 590 x 5				2950 4130.00 2655
8	Z	BP-BKT SUPPLY PHV STICKER				20.00
9	L	BP-LPO SUPPLY FRONT REGN PLATE (PO#)				80.00
10	1	U52119-47969 COVER, FR BUMPER CRU (Black)	1.00	589.50	25.00	442.12
11	2	U53102-47180 GRILLE SUB-ASSY, BR	1.00	597.00	25.00	447.75
12	3	U52611-47100 ABSORBER, FR BUMPER	1.00	84.20	25.00	63.15
13	4	U52021-47160 REINFORCEMENT x nn	1.00	696.00	25.00	522.00
14	5	U53111-47110 GRILLE, RADIATOR BR	1.00	510.10	25.00	382.57

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details					
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000037 / ICCUA2		M/S Grab Rentals Pte Ltd					
		Document No. 0		6 Battery Road #38-04 Singapore 049909					
		Document Date 18/01/2022		Work: 65703925					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	ZVW40R	AWXEBW Q3	23/02/2021	SMY1960L	0	12811	75/DS/SMY1960L		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDZS3EU10J059924		2ZR2F74130	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
15	6	U81140-47660	UNIT ASSY, HEADLAMP, <i>1 x nr</i>			1.00	2678.10	25.00	2008.57
16	7	U81070-47660	UNIT ASSY, HEADLAMP, <i>1 x nr</i>			1.00	2678.10	25.00	2008.57
17	8	U81210-47010	LAMP ASSY, FOG, RH <i>1 x nr</i>			1.00	329.00	25.00	246.75
18	9	U81220-47010	LAMP ASSY, FOG, LH <i>1 x nr</i>			1.00	313.00	25.00	234.75
19	0	U52159-47912	COVER, RR BUMPER <i>RR</i>			1.00	589.50	25.00	442.12
20	1	U52155-47010	SUPPORT, RR BUMPER <i>x nr</i>			1.00	151.20	25.00	113.40
21	2	U52156-47010	SUPPORT, RR BUMPER <i>RR</i>			1.00	151.20	25.00	113.40
22	3	U52591-47030	SEAL, RR BUMPER <i>1 x nr</i>			1.00	95.40	25.00	71.55
23	4	U52592-47030	SEAL, RR BUMPER <i>1 x nr</i>			1.00	136.80	25.00	102.60
24	5	U52023-12240	REINFORCEMENT <i>1 x nr</i>			1.00	230.20	25.00	172.65
25	6	U58307-47080	PANEL SUB-ASSY, BODY <i>1 x nr</i>			1.00	738.00	25.00	553.50
26	7	U61602-47131	PANEL SUB-ASSY, <i>x R</i>			1.00	1023.30	25.00	767.47
27	8	U58742-47020	PROTECTOR, QUARTER <i>- nec</i>			1.00	24.40	25.00	18.30
28	9	U67005-47460	PANEL SUB-ASSY, BACK <i>- DO</i>			1.00	1177.30	25.00	882.97
29	0	U67881-47040	WEATHERSTRIP, BACK <i>* BR CR4</i>			1.00	355.10	25.00	266.32
30	1	U68105-47190	GLASS SUB-ASSY, BACK <i>- BR</i>			1.00	1093.60	25.00	820.20
31	2	U56117-50140	DAM, WINDOW GLASS <i>- nec</i>			1.00	30.60	25.00	22.95
32	3	U67750-47050 C0	BOARD ASSY, BACK <i>x nr</i>			1.00	348.70	25.00	261.52
33	4	U81551-47262	LENS & BODY, RR <i>x nr</i>			1.00	730.90	25.00	548.17
34	5	U81561-47252	LENS & BODY, RR <i>RR</i>			1.00	706.10	25.00	529.57
For & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd									
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less			
						Amount Due			

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details				
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000037 / ICCUA2		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925				
Document No. 0		Document Date 18/01/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	ZVV40R	AWXEBW Q3	23/02/2021	SMY1960L	0	12811	75/DS/SMY1960L	
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On			
JTDZS3EU10J059924	2ZR2F74130	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00	
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount		
35	6	U81910-47010 REFLECTOR ASSY, <i>x nn</i>	1.00	63.40	25.00	47.55		
36	7	U81920-47010 REFLECTOR ASSY, <i>- RR</i>	1.00	63.40	25.00	47.55		
37	8	U76891-47040 SPOILER, RR NO.1 <i>* - RR</i>	1.00	899.70	25.00	674.77		
38	9	U76801-47140 E2 GARNISH SUB-ASSY, <i>x nn</i>	1.00	459.60	25.00	344.70		
39	0	U75310-33050 EMBLEM ASSY, <i>- RR</i>	1.00	112.30	25.00	84.22		
40	1	U75442-47080 PLATE, BACK DOOR <i>- RR</i>	1.00	67.20	25.00	50.40		
41	2	U75310-47020 EMBLEM ASSY, <i>- RR</i>	1.00	67.20	25.00	50.40		
42	3	U75441-47130 PLATE, LUGGAGE COMPT <i>* - RR</i>	1.00	58.00	25.00	43.50		
43	4	U75374-47112 EMBLEM, SIDE PANEL <i>x nn</i>	1.00	58.00	25.00	43.50		
44	5	TREVSE-47006 4X1 BACK SENSOR STEEL BLONDE ME <i>- RR</i>	1.00	101.05		75.79 101.05		
<i>Steve (LKK)</i> <i>ML ML</i> <i>18/1/22, 1:30pm</i> <i>10 days</i> <i>P/P</i> <i>Ly RL Ly</i>								
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Third party survey is on a "without prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____			Customer's Signature Please acknowledge receipt of vehicle		Charge Summary Parts 13,530.56 Labour 10,370.00 Sublet 260.00 Lubrication/Fluid 0.00 Others 0.00		Total 24,160.56 GST 7.00% 1,691.24 Less 0.00 Amount Due 25,851.80	

Customer Copy