



DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jan 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SFM8008L/17/01/2022 12:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front bumper	0.00	0.00	Ben *210.00 F
2	1		*1 pc front bumper RH fog lamp cover	0.00	0.00	m *55.00 F X
3	1		*1 pc front bumper RH side retainer	0.00	0.00	DTT *26.00 F
4	1		*6 pcs front bumper clips @ \$1.50/pc	0.00	0.00	m *9.00 F
5	1		*1 pc front bumper sponge	0.00	0.00	m *55.00 F X
6	1		*1 pc LH headlamp	0.00	0.00	W *260.00 F
7	1		*1 pc air resonator	0.00	0.00	m *55.00 F X
Total Parts (S\$)						670.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SFM8008L/17/01/2022 12:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Remove & refix frt bumper & attachments, grille,headlamp;knocking & repair frt panel & realign fender the same	New	2cd 400.00
2	Putty & respray frt bumper & attachments,fender,frt panel & all affected areas	New	2cd 500.00
Gross Labour Cost (S\$)			900.00

Cheng Hoe Motor Pte Ltd/SFM8008L/17/01/2022 12:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

8905.00