

ASS. REC. BY:

REF:

C121

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1-B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S12M 8008L

Yr Regn:

12, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis

c.c

1598

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

282525

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

HR053REL4-10563070

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Tourada

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

4/12/21

D.O.I.

17/1/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$


☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER:
NA

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
Policy No:
Vehicle Reg. No.: **SFM8008L**
Party At Fault: UNKNOWN
Driver (TP): LUM CHAN SENG

Ref. No: TP/CHINA (GBK9956B)
Date of Loss: 04/12/2021
Driveable?

Make/Model: TOYOTA COROLLA ALTIS, 1.6 (A)
Vehicle Colour: SILVER
Engine No: 1ZRY348818
Odometer: 0 KM

Vehicle Reg. Date: 19/12/2016
Chassis No: MR053REH104563070

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 0

*Not with other
Return by paint
2 days*

Description of Accident/Loss: REFER TO CLAIM FORM
Remarks: VEHICLE AT ANG MO KIO WORKSHOP
Present Location: CHENG HOE MOTOR PTE LTD (AMK)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

COST OF CLAIMS

	Acknowledged by Repairer	Amount
Parts	Signature:	670.00
Miscellaneous Items	Date:	0.00
Labour		900.00
Paintwork Labour		0.00
Towing		0.00

Gross Total (S\$) 1,570.00
+ GST 7.00% (S\$) 109.90
Nett Amount (S\$) 1,679.90

This claim is handled by: DORLYN LI YAZHU

Reference
 Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jan 2022)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merlmen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SFM8008L/17/01/2022 12:10
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front bumper	0.00	0.00	Bu *210.00 F
2	1		*1 pc front bumper RH fog lamp cover	0.00	0.00	m *55.00 F X
3	1		*1 pc front bumper RH side retainer	0.00	0.00	DIY *28.00 F ✓
4	1		*6 pcs front bumper clips @ \$1.50/pc	0.00	0.00	m *9.00 F
5	1		*1 pc front bumper sponge	0.00	0.00	*55.00 F ?
6	1		*1 pc LH headlamp	0.00	0.00	W *280.00 F ✓
7	1		*1 pc air resonator	0.00	0.00	m *55.00 F X
Total Parts (\$\$)						670.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SFM8008L/17/01/2022 12:10. Not valid without Reference section.
 Generated using Merlmen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Remove & refix frt bumper & attachments, grille, headlamp; knocking & repair frt panel & realign fender the same	New	200 400.00
2	Putty & respray frt bumper & attachments, fender, frt panel & all affected areas	New	200 500.00
Gross Labour Cost (\$\$)			900.00

Cheng Hoe Motor Pte Ltd/SFM8008L/17/01/2022 12:10. Not valid without Reference section.
 Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The acceptance and completion of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the completion of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 06/12/2021 13:01 (SGT)
Date of Accident 04/12/2021 15:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information OPEN SPACE CARPARK MARINE COVE, EAST COAST PARK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFM8008L

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LUM CHAN SENG
NRIC No S0147924E
Email Address PATCSLUM@GMAIL.COM
Mobile Phone No (Phone) +65-97656066
Alternative Phone No +65-97656066

VEHICLE PARTICULARS

Manufacturer Toyota
Model Corolla
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1600


INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5114372427-01
Cover Note Number -

DRIVER

Name of Driver LUM CHAN SENG
NRIC No S0147924E

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Large lined area for describing the circumstances of the accident, currently blank.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time 06122021 & 1330Hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Md Ikhsan

NRIC/FIN No.: S098395