

REC BY: Taufik

REF:

CS/AM 22000643/Tng3

ASSIGNMENT

From: _____ Date: _____
 Estimated cost: _____
 OD ☒ P / IS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJR7722R Yr Regn: 2016 July
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Vezel Hybrid cc 1496
 Colour: Blue A/C: Insured / Std / Nil / NA
 Sp. Reading: 227250 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: R431118557
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modl: Nil / SRim / STD A/Rim or _____
 Tyre Size: F: 215/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU ☒ RIR / SUMI /
 TOYO / YOKO or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$60k
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lurn Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS wp
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.L. 20/1/22
 Survey held at TSL Auto
 Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or
Fit N/S, u/c
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufik confirmed Lump Sum \$5850 and 6 days (Red. \$18783.20, 76%)

Date/Time, File Pass to? ☐ : Preli. Report
23/2/23 ☐ : Final Report

Date/Time, File Return to?

Format: TP
 Prop Sum / L.B.k. P: 5850

Days Of Repair: 6
 Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)

Survey Fee: _____
 Transportation: _____
 S + RS: _____
 Photos: _____
 Others: _____

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJR7722R Honda Vezel

			Estimated
No.	Qty.	Parts Description	Parts Price
1	1	Front bumper assy	\$ 1,290.00 <i>de</i> 765
2	1	Front bumper left bracket	\$ 44.00 <i>x un</i>
3	1	Front bumper left retainer	\$ 46.00 <i>de</i>
4	1	Front bumper reinforcement	\$ 393.00 <i>x</i>
5	1	Front bumper lower grille	\$ 174.00 <i>x</i>
6	1	Front left reinforcement bracket	\$ 193.00 <i>x un</i>
7	1	Front bumper tow cover	\$ 88.00 <i>x</i>
8	1	Front left fog lamp	\$ 280.00 <i>x</i>
9	1	Front left fog lamp garnish	\$ 121.00 <i>de</i> 69
10	1	Front grille assy	\$ 382.00 <i>x un</i>
11	1	Front grille emblem	\$ 105.00 <i>x un</i>
12	1	Front left headlamp	\$ 1,478.00 <i>one</i>
13	1	Front left headlamp bracket	\$ 161.00 <i>x un</i>
14	1	Front bonnet assy	\$ 1,681.00 <i>R x</i>
15	2	Front bonnet hinges	\$ 190.00 <i>x</i>
16	1	Front bonnet insulator	\$ 291.00 <i>x un</i>
17	1	Front bonnet lock mechanism	\$ 156.00 <i>x</i>
18	1	Front left fender assy	\$ 682.00 <i>bt</i> 586
19	1	Front left fender inner cowl	\$ 278.00 <i>x un</i>
20	1	Front left fender protector	\$ 198.00 <i>de</i>
21	1	Front left fender 'hybrid' emblem	\$ 68.00 <i>de</i>
22	1	Front support panel assy	\$ 1,164.00 <i>x</i>
23	1	Front support panel top garnish	\$ 205.00 <i>x</i>
24	2	Front support panel side garnish	\$ 168.00 <i>x un</i>
25	1	Front support panel lower bracket	\$ 106.00 <i>x</i>
26	1	Front left suspension assy	\$ 780.00 <i>bt</i> 520
27	1	Front left knuckle arm	\$ 460.00 <i>bt</i>
28	1	Front left wheel bearing	\$ 252.00 <i>bt</i>
29	1	Front left lower arm	\$ 430.00 <i>bt</i>
30	1	Front left wheel hub	\$ 299.00 <i>x un</i>
31	1	Front left door wing mirror complete assy	\$ 978.00 <i>dis</i> 813
32	1	Front left door assy	\$ 1,481.00 <i>R x</i>
33	2	Front left door hinges	\$ 165.00 <i>x</i>
34	1	Front left door checker linkage	\$ 186.00 <i>x</i>
35	1	Front left door regulator with motor	\$ 483.00 <i>x</i>
36	1	Front left door inner trim board	\$ 690.00 <i>x</i>
37	1	Front left door glass outer moulding	\$ 195.00 <i>x</i>
38	1	Front left door outer handle	\$ 382.00 <i>x</i>
39	1	Front left door lock mechanism	\$ 288.00 <i>x</i>
40	1	Front left door weatherstrip	\$ 188.00 <i>x</i>
41	1	Left side sill panel	\$ 1,680.00 <i>x</i>
less 20%			\$ 18,879.00
			\$ 3,775.80
			\$ 15,103.20

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJR7722R Honda Vezel

No. Qty. Parts Description			Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Front bumper clips	\$ 60.00 <i>3 over</i>
2	6	Front grille clips	\$ 40.00 <i>x un</i>
3	1	Front bumper lower spoiler	\$ 1,450.00 <i>500 out</i>
4	10	Front bumper lower spoiler clips	\$ 50.00 <i>x un</i>
5	1	Front bumper lower spoiler sealant	\$ 100.00 <i>3 over</i>
6	4	Front bumper lower grille clips	\$ 30.00 <i>x un</i>
7	1	Front no plate with garnish	\$ 100.00 <i>x un</i>
8	6	Front left fender inner cowling clips	\$ 50.00 <i>x un</i>
9	6	Front left fender protector clips	\$ 50.00 <i>x un</i>
10	1	Front left sport rim	\$ 750.00 <i>out 500</i>
11	1	Front left tyre	\$ 350.00 <i>x un</i>
12	1	Front no plate with garnish	\$ 100.00 <i>x un</i>
13	6	Front support panel top garnish clips	\$ 40.00 <i>x un</i>
14	8	Front bonnet insulator clips	\$ 50.00 <i>x un</i>
15	1	Front left skirting	\$ 1,400.00 <i>x un</i>
16	16	Front left skirting clips	\$ 80.00 <i>x un</i>
17	1	Front left skirting sealant	\$ 120.00 <i>x un</i>
18	1	Front left skirting chrome garnish	\$ 450.00 <i>x un</i>
19	8	Front left door inner trim board clips	\$ 50.00 <i>x un</i>
			<u>\$ 5,320.00</u>
Total parts			\$ 20,423.20

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJR7722R Honda Vezel

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	\$ 1,400.00 600
2	To putty and spray painting front left portion.	\$ 1,400.00 800
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To remove and install front bonnet lock mechanism.	\$ 80.00 Km
5	To apply anti rust proofing to front left affected area.	\$ 140.00 30
6	To remove and install front left undercarriage parts.	\$ 350.00 150
7	To balance front left wheel.	\$ 50.00 30
8	To conduct wheel alignment.	\$ 120.00 80
9	To synchronise front left wing mirror for function.	\$ 120.00 30
10	To remove and install front left door lock mechanism .	\$ 80.00 Xun
11	To check front left door central locking for function.	\$ 80.00 Xun
12	To transfer front left door glass to new door.	\$ 80.00 Xun
13	To remove and install front left door sun visor.	\$ 80.00 Xun
14	To remove and install front left door regulator with motor assy.	\$ 80.00 Xun
15	Towing service.	\$ 100.00 Xun
Total labour :		\$ 4,210.00

Total parts : \$ 20,423.20

Total labour : \$ 4,210.00

Total repair cost : \$ 24,633.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

o Cdey