

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowork@gmail.com



PERFECT
AUTOWORK
PTE LTD

DATE : 14.01.2022

TO : **ERGO** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMR8182G**
MODEL : **HONDA FIT**
DATE OF ACCIDENT : 15.01.2022
TIME OF ACCIDENT : 12:00HRS

Denise

GIC31351947

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR FENDER RH <i>Repair</i>	1	\$ 559.20	\$ 559.20
2	REAR FENDER INNER COWLING <i>New</i>	2	\$ 69.20	\$ 138.40
3	REAR FENDER 1/4 GLASS WITH MOULDING RH <i>New</i>	1	\$ 279.40	\$ 279.40
4	REAR FENDER INNER TRIM RH <i>New</i>	1	\$ 594.20	\$ 594.20
5	REAR FENDER AIR VENT RH <i>New could</i>	1	\$ 49.20	\$ 49.20
6	REAR FENDER INNER PANEL RH <i>New</i>	1	\$ 764.30	\$ 764.30
7	REAR WHEEL CAP <i>New</i>	2	\$ 175.20	\$ 350.40
8	REAR AXLE <i>New</i>	1	\$ 1,210.80	\$ 1,210.80
9	REAR SHOCK ABSORBER <i>New</i>	2	\$ 359.90	\$ 719.80
10	REAR WHEEL HUP C/W BEARING <i>New</i>	2	\$ 294.60	\$ 589.20
11	REAR BUMPER <i>Dehid</i>	1	\$ 592.40	\$ 592.40
12	REAR BUMPER LOWER CENTER GARNISH <i>New</i>	1	\$ 130.40	\$ 130.40
13	REAR BUMPER SIDE COVER GARNISH RH <i>New</i>	1	\$ 69.20	\$ 69.20
14	REAR BUMPER SIDE RETAINER <i>New could 12H</i>	2	\$ 39.20	\$ 78.40
15	TAIL LAMP RH <i>could</i>	1	\$ 293.20	\$ 293.20
16	REAR END PANEL <i>New</i>	1	\$ 390.40	\$ 390.40
17	REAR END PANEL TOP GARNISH <i>New</i>	1	\$ 120.60	\$ 120.60

876.60

701.28

TOTAL PRICE \$ 6,929.50
LESS 20% \$ 1,385.90
SUB TOTAL PRICE \$ 5,543.60

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR FENDER SEALANT RH <i>New New</i>	1	\$ 150.00	\$ 150.00

TO : **ERGO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMR8182G**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 15.01.2022
 TIME OF ACCIDENT : 12:00HRS

2	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>X</i>
3	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>f</i>
4	REAR FENDER INNER UPPER TRIM (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>X</i>
5	REAR FENDER QUARTER GLASS SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	<i>f</i>
6	REAR FENDER QUARTER GLASS INNER SHIELD <i>new</i>	2	\$ 60.00	\$ 120.00	<i>f</i>
7	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 150.00	\$ 150.00	<i>30</i>
8	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
9	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	<i>X</i>
10	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	<i>f</i>
11	REAR WHEEL RIM <i>new</i>	1	\$ 550.00	\$ 550.00	<i>400</i>
12	REAR WHEEL TYRE <i>new</i>	1	\$ 350.00	\$ 350.00	<i>f</i>
13	BRAKE OIL <i>new</i>	1	\$ 40.00	\$ 40.00	<i>X</i>

440

TOTAL \$ 2,160.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	<i>300</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>400</i>
3	TUFF COAT	\$ 250.00	<i>50</i>
4	WIRING, BULB CHECKING	\$ 180.00	<i>30</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>X</i>
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>X</i>
7	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	<i>X</i>
8	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>X</i>
9	REMOVE AND REFIX REAR RH FENDER GLASS	\$ 120.00	<i>X</i>
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>

TO : ERGO MOTOR CLAIMS DEPTS
VEHICLE NO : SMR8182G
MODEL : HONDA FIT
DATE OF ACCIDENT : 15.01.2022
TIME OF ACCIDENT : 12:00HRS

11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

830

TOTAL \$ 4,850.00

Adrian C
h/s 15/03/22.

03 days

total: 1971.28

h/s: 1.5K.

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,703.60
TOTAL LABOUR COST : \$ 4,850.00
TOTAL REPAIR COST : \$ 12,553.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: