

Claim	S2M03R2H
Reference	CS3/ASM22000646/Evy3e2
Loss Date	12 January 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Incident Only
Report Date	14 Jan 2022 1:50:48 PM
Request Date	14 January 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SLR1698T
Vehicle	
Registration #	
Make	TPVD Mazda
Model	6

Service Address

, , ,

Primary Contact/Insured

SHAHBIN MUHAMMAD AIDIL BIN
BLK 209 YISHUN STREET 21, #02-143, 760209,
Singapore
87771747

Owner Default

test@axa.com

Additional Instructions

Messages4

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

 Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2200525.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2022
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2022

FAQ

English (SG) ▾

Elaine Kuan ▾

Home

Service Requests

...

ence

Photos

		SUBTYPE	AUTHOR	DATE UPLOADED
			LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2022
 SLR 1698T IA PRS.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 January 2022
 LKKPhotosIn4.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	19 January 2022
 EMAIL FROM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	14 January 2022
 FBS205C INSD GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	14 January 2022
 SLR1698T TP GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	14 January 2022